



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Blue
Year of manufacture	2005
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	168 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2022-08-01
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	48
Total items failed	14

MOT #18	2021-08-02 11:20
MOT test number	852690109468
Result	✓ Passed
Next expiry date	2022-08-01

MOT #17	2021-08-02 07:57
MOT test number	744447549002
Result	✗ Failed
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #16	2020-10-20 15:57
MOT test number	930647255768
Result	✓ Passed

**MOT #15**

2019-04-16 10:35

MOT test number

131865699493

Result

✓ Passed

Advice Offside front tyre 3mm and wearing low on edges**Advice** Nearside rear tyre sidewall perished**Advice** Nearside front tyre 3/4mm and perished**MOT #14**

2018-04-13 14:42

MOT test number

822417137423

Result

✓ Passed

Advice O/s/r tyre under inflated**Advice** Play in steering system**Advice** Both rear axle mounting bushes unbonded, not resulting in excessive movement**Advice** Free play at steering wheel, knocking when rocked**Advice** O/s/f tyre wear to edges**Advice** Cracking to sidewalls and tread of both rear tyres**Advice** Drivers wiper arm/linkage worn**Advice** Both rear coil springs corroded**Advice** N/s/f tyre wear to edges, cracking to sidewalls and tread**Advice** Surface corrosion to various brake pipes**Advice** Smear from n/s wiper**Advice** Wear to front brake discs**Advice** Engine oil over full



MOT #13

2018-04-12 13:58

MOT test number

269233428346

Result		✗ Failed
Advice	Engine oil over full	
Advice	Coolant expansion bottle empty	
Advice	O/s/r tyre under inflated	
Fail	Offside rear brake binding (3.7.B.1)	
Advice	Surface corrosion to various brake pipes	
Advice	Play in steering system	
Advice	Wear to front brake discs	
Advice	Free play at steering wheel, knocking when rocked	
Advice	Drivers wiper arm/linkage worn	
Advice	Cracking to sidewalls and tread of both rear tyres	
Fail	Front registration plate insecure (6.3.1b)	
Advice	Both rear axle mounting bushes unbonded, not resulting in excessive movement	
Advice	Both rear coil springs corroded	
Fail	Offside Headlamp aim beam image obviously incorrect lens discoloured (1.8.A.1b)	
Advice	O/s/f tyre wear to edges	
Advice	N/s/f tyre wear to edges, cracking to sidewalls and tread	
Advice	Smear from n/s wiper	

**MOT #12**

2017-03-24 11:43

MOT test number

184795018946

Result

✓ Passed

Advice Front number plate slightly damaged**Advice** Centre and rear exhaust sections corroding**Advice** N/s/f tyre outer side wall perishing**MOT #11**

2017-03-23 16:00

MOT test number

217370987965

Result

✗ Failed

Fail Nearside rear brake binding (3.7.B.1)**Advice** N/s/f tyre outer side wall perishing**Fail** Rear brake application uneven (3.7.B.2)**Advice** Front number plate slightly damaged**Advice** Centre and rear exhaust sections corroding**MOT #10**

2016-04-12 12:43

MOT test number

720032246811

Result

✓ Passed

MOT #9

2015-06-26 09:47

MOT test number

696357275147

Result

✓ Passed

**MOT #8** 2013-06-21 13:57**MOT test number** 258532073421**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust rattle**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-06-20 12:39**MOT test number** 538001273179**Result** ✗ Failed**Advice** Nearside Front front brake grabbing slightly (3.7.A.2b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust rattle**Fail** Offside Front front brake grabbing severely (3.7.A.2b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2012-05-24 11:47**MOT test number** 705735142121**Result** ✓ Passed**MOT #5** 2011-06-06 12:18**MOT test number** 838197351137**Result** ✓ Passed

**MOT #4** 2011-06-06 10:44**MOT test number** 445567651142**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2010-06-23 13:29**MOT test number** 174924870154**Result** ✓ Passed**MOT #2** 2009-03-23 11:11**MOT test number** 120792489044**Result** ✓ Passed**MOT #1** 2008-04-01 09:37**MOT test number** 101902698479**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
15 March 2022

X

MOT

Expired:
1 August 2022

Tax status	Expired at 15 March 2022
Days left	776 days too late
MOT expiry date	1 August 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	WN05UCU
Plate since	2019-03-28
Current registration	WN05UCU
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-04-19
Last registration	2021-08-02
Complete history	See info



Registration #1	2005-04-19	21 mi
Registration #2	2008-04-01	15.062 mi
Registration #3	2009-03-23	17.713 mi
Registration #4	2010-06-23	21.851 mi
Registration #5	2011-06-06	27.042 mi
Registration #6	2011-06-06	27.042 mi
Registration #7	2012-05-24	31.864 mi
Registration #8	2013-06-20	36.668 mi
Registration #9	2013-06-21	36.673 mi
Registration #10	2015-06-26	39.977 mi
Registration #11	2015-06-26	39.977 mi
Registration #12	2015-06-26	39.977 mi
Registration #13	2015-06-26	39.977 mi
Registration #14	2015-06-26	39.977 mi
Registration #15	2015-06-26	39.977 mi
Registration #16	2015-06-26	39.977 mi
Registration #17	2015-06-26	39.977 mi
Registration #18	2015-06-26	39.977 mi
Registration #19	2015-06-26	39.977 mi
Registration #20	2015-06-26	39.977 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZ1937426