



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R
Colour	Black
Year of manufacture	2010
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 4

Date	2022-03-16
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 3

Date	2021-12-03
Pictures	42
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 2

Date	2021-06-28
Pictures	42
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-27
Pictures	42

CarCheck.co.uk

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-03-15
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	21
Total items failed	6

MOT #16	2024-03-13 16:16
MOT test number	191342369633
Result	✓ Passed
Next expiry date	2025-03-15
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2023-03-14 16:00
MOT test number	347200481140
Result	✓ Passed

MOT #14	2022-03-16 14:00
MOT test number	717230329552
Result	✓ Passed

MOT #13	2021-06-26 14:35
MOT test number	221888534292
Result	✓ Passed

**MOT #12** 2020-08-29 08:37**MOT test number** 770910978361**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2019-09-06 15:45**MOT test number** 152282450441**Result** ✓ Passed**MOT #10** 2019-09-06 08:01**MOT test number** 117698282435**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2018-09-08 09:16**MOT test number** 481226336371**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))**MOT #8** 2017-09-16 11:51**MOT test number** 649497070330**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2017-09-16 11:51**MOT test number** 111298815370**Result** ✗ Failed**Pass with rectification** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2016-09-08 15:05**MOT test number** 473331146044**Result** ✓ Passed**MOT #5** 2015-09-09 12:03**MOT test number** 572389770569**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #4** 2014-08-30 11:26**MOT test number** 677792944230**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-09-16 16:26**MOT test number** 659929953270**Result** ✓ Passed**MOT #2** 2013-05-24 11:23**MOT test number** 828794743143**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-05-24 11:23**MOT test number** 565634243167**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
15 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	15 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-05-25
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2010-05-25	26 mi
Registration #2	2013-05-24	49.336 mi
Registration #3	2013-09-16	55.265 mi
Registration #4	2014-08-30	61.236 mi
Registration #5	2015-09-09	67.243 mi
Registration #6	2016-09-08	76.351 mi
Registration #7	2017-09-16	82.929 mi
Registration #8	2017-09-16	82.929 mi
Registration #9	2018-09-08	94.311 mi
Registration #10	2019-09-06	105.375 mi
Registration #11	2019-09-06	105.375 mi
Registration #12	2019-09-06	105.375 mi
Registration #13	2019-09-06	105.375 mi
Registration #14	2019-09-06	105.375 mi
Registration #15	2019-09-06	105.375 mi
Registration #16	2019-09-06	105.375 mi
Registration #17	2019-09-06	105.375 mi
Registration #18	2019-09-06	105.375 mi
Registration #19	2019-09-06	105.375 mi
Registration #20	2019-09-06	105.375 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4335 mm
Wheel base	2560 mm
Kerb weight	1650 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2AF0293588