



report date: 2024-03-28

General information

|                     |                 |
|---------------------|-----------------|
| Make                | VOLVO           |
| Model               | S60 D2 R-DESIGN |
| Colour              | Black           |
| Year of manufacture | 2011            |
| Top speed           | 121 mph         |
| 0 - 60 mph          | 10.7 seconds    |
| Gearbox             | 6 speed Manual  |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 113 BHP             |
| Max. torque             | 270 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 54.3 mpg            |
| Consumption extra urban | 74.3 mpg            |
| Consumption combined    | 65.7 mpg            |
| CO2 emission            | 114 g/km            |
| CO2 label               | C                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-12-07                  |
| Pictures      | 32                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-03-10 |
| MOT pass rate      | 73 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 4          |
| Total advice items | 24         |
| Total items failed | 1          |

|         |                  |
|---------|------------------|
| MOT #15 | 2024-02-23 10:56 |
|---------|------------------|

|                 |              |
|-----------------|--------------|
| MOT test number | 824049752696 |
|-----------------|--------------|

|        |          |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

|                  |            |
|------------------|------------|
| Next expiry date | 2025-03-10 |
|------------------|------------|

- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #14**

2024-02-23 10:56

**MOT test number**

627764942942

**Result**

✗ Failed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #13**

2023-03-02 14:30

**MOT test number**

688803492130

**Result**

✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2022-02-11 08:34

**MOT test number**

992882886541

**Result**

✓ Passed

**MOT #11** 2022-02-08 17:48**MOT test number** 661101139846**Result** ✗ Failed

- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #10** 2021-03-11 15:31**MOT test number** 636175300953**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-12-03 11:26**MOT test number** 298048799587**Result** ✓ Passed**MOT #8** 2019-12-02 11:17**MOT test number** 307709657363**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-03-06 10:01**MOT test number** 738019313782**Result** ✓ Passed



|  |                  |
|--|------------------|
| <b>MOT #6</b>  | 2019-03-05 13:58 |
| <b>MOT test number</b>   | 459704832129     |
| <b>Result</b>  | ✗ Failed         |
| <b>DANGEROUS</b> Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))            |                  |
| <b>MAJOR</b> Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) |                  |

|                        |                  |
|------------------------|------------------|
| <b>MOT #5</b>          | 2018-02-02 15:44 |
| <b>MOT test number</b> | 772800009593     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #4</b>          | 2017-02-03 16:06 |
| <b>MOT test number</b> | 920224364220     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #3</b>          | 2016-07-30 08:15 |
| <b>MOT test number</b> | 633463969502     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #2</b>          | 2015-08-04 10:08 |
| <b>MOT test number</b> | 607186415219     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #1</b>          | 2014-08-13 15:06 |
| <b>MOT test number</b> | 397855824243     |
| <b>Result</b>          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
10 March 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 305                             |
| <b>MOT expiry date</b>  | 10 March 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | C              |
| <b>Single payment (12 months)</b>              | £ 35,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 36,75,-      |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2019-01-01    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2019-01-01    |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2011-09-05               |
| Last registration          | 2024-02-23               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2011-09-05 | 13 mi     |
| Registration #2  | 2014-08-13 | 44.152 mi |
| Registration #3  | 2015-08-04 | 60.500 mi |
| Registration #4  | 2016-07-30 | 69.489 mi |
| Registration #5  | 2017-02-03 | 73.204 mi |
| Registration #6  | 2018-02-02 | 79.198 mi |
| Registration #7  | 2019-03-05 | 85.375 mi |
| Registration #8  | 2019-03-06 | 85.376 mi |
| Registration #9  | 2019-12-02 | 88.449 mi |
| Registration #10 | 2020-05-20 | 95.377 mi |
| Registration #11 | 2020-05-20 | 95.377 mi |
| Registration #12 | 2020-05-20 | 95.377 mi |
| Registration #13 | 2020-05-20 | 95.377 mi |
| Registration #14 | 2020-05-20 | 95.377 mi |
| Registration #15 | 2020-05-20 | 95.377 mi |
| Registration #16 | 2020-05-20 | 95.377 mi |
| Registration #17 | 2020-05-20 | 95.377 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 91%                             |
| Children       | 78%                             |
| Pedestrian     | 26%                             |
| Safety systems | 71%                             |
| Overall rating | 73%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1782 mm |
| Height              | 1447 mm |
| Length              | 4266 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1359 kg |
| Max. allowed weight | 1780 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 52 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 3                |
| Number of seats    | 4                |

|                 |         |
|-----------------|---------|
| Number of axles | 2       |
| Engine number   | 1708102 |