



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MODUS PRIVILEGE 16V
Colour	Gold
Year of manufacture	-
Top speed	114 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	151 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-28
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #23	2021-11-30 14:11
MOT test number	512240340126
Result	✓ Passed
Next expiry date	2022-11-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2021-11-29 13:00
MOT test number	654455332801
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #21	2020-11-30 11:33
MOT test number	956752747581
Result	✓ Passed

**MOT #20** 2020-11-27 12:30**MOT test number** 446151290318**Result** ✗ Failed

- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #19 2019-11-29 15:49**MOT test number** 604798456142**Result** ✓ Passed**MOT #18** 2019-11-29 13:38**MOT test number** 409064507474**Result** ✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #17 2018-11-29 14:31**MOT test number** 345603752142**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #16	2018-11-27 13:07
MOT test number	296086507621
Result	✗ Failed
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Position lamp showing white light to the rear lens damaged (4.2.3 (a) (ii))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15	2017-11-28 16:06
MOT test number	623013824984
Result	✓ Passed
Advice	Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
Advice	Offside front tyre scrubbed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #14**

2017-11-27 10:04

MOT test number

322322586117

Result**✗ Failed**

- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Fail** Rear brake application uneven (3.7.B.2)
- Advice** Offside rear wheel tight to turn by hand
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Central Upper Stop lamp not working (1.2.1b)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Hazard warning lamps inoperative (1.4.B.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Nearside rear wheel tight to turn by hand
- Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Fail** Offside front brake excessively fluctuating (3.7.B.3)
- Advice** Offside front tyre scrubbed
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Direction indicator not working (1.4.A.2c)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #13** 2016-11-28 09:16**MOT test number** 423020013281**Result** ✓ Passed**MOT #12** 2016-02-16 11:11**MOT test number** 529568434310**Result** ✓ Passed**MOT #11** 2015-02-17 16:10**MOT test number** 916808845054**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2015-02-17 10:53**MOT test number** 788928945011**Result** ✗ Failed**Fail** Offside rear brake binding (3.7.B.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #9** 2014-01-23 11:40**MOT test number** 825593024002**Result** ✓ Passed

**MOT #8** 2014-01-22 10:22**MOT test number** 666982724075**Result** ✗ Failed**Fail** Stop lamp not working (1.2.1b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #7** 2013-01-22 09:48**MOT test number** 109912723086**Result** ✓ Passed**MOT #6** 2013-01-22 09:48**MOT test number** 725182623004**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2012-02-16 10:11**MOT test number** 548507042069**Result** ✓ Passed**MOT #4** 2011-02-17 12:38**MOT test number** 729198041083**Result** ✗ Failed**Pass with rectification** Nearside Front constant velocity joint is insecure (2.5.C.1b)**MOT #3** 2011-02-17 12:38**MOT test number** 875348441020**Result** ✓ Passed



MOT #2	2010-04-06 13:46
MOT test number	434546490070
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-04-07 17:04
MOT test number	954717599086
Result	✓ Passed
Notice	Corrosion on brake discs
Advice	Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Front brake pads getting low



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-10
Last registration	2021-11-30
Complete history	See info



Registration #1	2005-05-10	22 mi
Registration #2	2009-04-07	43.233 mi
Registration #3	2010-04-06	50.353 mi
Registration #4	2011-02-17	50.947 mi
Registration #5	2012-02-16	53.597 mi
Registration #6	2013-01-22	55.876 mi
Registration #7	2014-01-22	58.736 mi
Registration #8	2014-01-23	58.736 mi
Registration #9	2015-02-17	61.515 mi
Registration #10	2015-02-17	61.515 mi
Registration #11	2016-02-16	64.224 mi
Registration #12	2016-11-28	66.304 mi
Registration #13	2016-11-28	66.304 mi
Registration #14	2016-11-28	66.304 mi
Registration #15	2016-11-28	66.304 mi
Registration #16	2016-11-28	66.304 mi
Registration #17	2016-11-28	66.304 mi
Registration #18	2016-11-28	66.304 mi
Registration #19	2016-11-28	66.304 mi
Registration #20	2016-11-28	66.304 mi
Registration #21	2016-11-28	66.304 mi
Registration #22	2016-11-28	66.304 mi
Registration #23	2016-11-28	66.304 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1960 mm
Height	1589 mm
Length	3792 mm
Wheel base	2482 mm
Kerb weight	1205 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D005057