



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK350 AVANTGARDE
Colour	Black
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 3.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.7 mpg
CO2 emission	241 g/km
CO2 label	L






Internet history

Entry 3

Date	2022-01-18
Pictures	22
Listing price	View report



source: [yesauto.com](#)

Entry 2

Date	2021-11-11
Pictures	23
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-11-10
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-26
MOT pass rate	63 %
MOT passed	17
Failed MOT tests	10
Total advice items	119
Total items failed	26

MOT #27	2024-01-24 12:55
MOT test number	467238986807
Result	✓ Passed
Next expiry date	2025-01-26
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Front Brake pad(s) wearing thin inner pads (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #26**

2024-01-24 12:55

MOT test number

232776650109

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Front Brake pad(s) wearing thin inner pads (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #25

2023-01-27 12:49

MOT test number

294258987123

Result**✓ Passed****MOT #24**

2022-08-30 15:52

MOT test number

661425455125

Result**✓ Passed**

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #23

2022-08-27 14:20

MOT test number

936216124950

Result**✗ Failed**

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #22**

2021-10-13 10:01

MOT test number

601481073062

Result

✓ Passed

- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Lower Suspension component pin or bush slightly worn hub (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #21

2021-10-12 11:45

MOT test number

590569900030

Result

✗ Failed

- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Lower Suspension component pin or bush slightly worn hub (5.3.4 (a) (i))

**MOT #20**

2020-12-08 14:47

MOT test number

410277253889

Result

✓ Passed

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Rear handbrake poor**Advice** Nearside Rear Suspension component pin or bush slightly worn lower hub bush (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #19**

2019-12-02 11:07

MOT test number

188023861379

Result

✓ Passed

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Forward compliance bush splitting. (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1
(b) (i))**Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Forward compliance bush splitting (5.3.4 (a) (i))

**MOT #18**

2019-12-02 10:44

MOT test number

466561028606

Result**✗ Failed**

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Forward compliance bush splitting (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Forward compliance bush splitting. (5.3.4 (a) (i))
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #17

2018-12-03 13:04

MOT test number

520542179221

Result**✓ Passed**

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #16**

2018-11-29 10:56

MOT test number

454482716582

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #15

2017-11-06 17:09

MOT test number

918141027991

Result**✓ Passed**

- Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)
- Advice** Offside Front Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #14**

2017-11-02 16:14

MOT test number

804063370706

Result**✗ Failed**

- Fail** Offside Outer Front suspension has excessive play in a lower suspension ball joint Rear track arm (2.5.B.1a)
- Advice** Offside Front Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)
- Fail** Offside Headlamp aim too high (1.8)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front brakes imbalanced on light and moderate braking (n/s reading 40% less)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Propshaft fouling under heatshields within transmission tunnel.
- Fail** Nearside Outer Front suspension has excessive play in a lower suspension ball joint Rear track arm (2.5.B.1a)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #13

2016-11-16 17:27

MOT test number

229649581213

Result**✓ Passed**

- Advice** Offside Front Upper Suspension arm has slight play in a pin/bush front arm inner bush (2.4.G.2)
- Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)
- Advice** Centre exhaust pipe rear mounting broken but system still supported



MOT #12

2015-11-23 16:59

MOT test number

949160954474

Result		✓ Passed
Advice	Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Rear exhaust hanger broken	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Oil leak	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)	



MOT #11

2015-11-23 16:45

MOT test number

848844465414

Result

✗ Failed

- Advice

Parking brake lever has little reserve travel (3.1.6b)
- Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice

Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Rear exhaust hanger broken
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)
- Advice

Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice

Oil leak
- Fail

Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #10** 2014-11-17 14:32**MOT test number** 366731824314**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Both rear tyres worn on inner edge**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Rear exhaust bracket broken**Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)**MOT #9** 2013-11-25 16:32**MOT test number** 487699023404**Result** ✓ Passed**Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #8** 2012-10-19 12:49**MOT test number** 687123392245**Result** ✓ Passed**MOT #7** 2011-11-17 16:21**MOT test number** 526591221302**Result** ✓ Passed

**MOT #6** 2010-12-23 15:57**MOT test number** 152137950322**Result** ✓ Passed**MOT #5** 2010-12-23 14:26**MOT test number** 311527250374**Result** ✗ Failed

- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

MOT #4 2009-11-11 17:21**MOT test number** 231615519360**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Large under trays
- Notice** Nearside rear brake pipe fitted to bracket [bent]
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Front and rear number/plates has very slight back ground markings

**MOT #3** 2009-11-11 16:29**MOT test number** 371175719308**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly damaged (3.6.B.2c)**Notice** Front and rear number/plates has very slight back ground markings**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Large under trays**Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2008-06-13 08:31**MOT test number** 974485968143**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Large under trays



MOT #1	2008-06-12 14:47
MOT test number	802864868192
Result	✗ Failed
Notice	Removed box from under felt under pedal
Pass with rectification	Nearside Front Headlamp aim too high and too far to the right. (1.8)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Large under trays
Fail	Nearside Rear rear brake recording little or no effort (3.7.B.5a)
Pass with rectification	Offside Front Headlamp aim too high (1.8)
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
26 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	26 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history



For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	31
First mileage registration	2005-07-11
Last registration	2024-01-24
Complete history	See info



Registration #1	2005-07-11	21 mi
Registration #2	2008-06-12	30.156 mi
Registration #3	2008-06-13	30.158 mi
Registration #4	2009-11-11	42.293 mi
Registration #5	2009-11-11	42.293 mi
Registration #6	2010-12-23	49.506 mi
Registration #7	2010-12-23	49.506 mi
Registration #8	2011-11-17	55.195 mi
Registration #9	2012-10-19	61.994 mi
Registration #10	2013-11-25	70.939 mi
Registration #11	2014-11-17	81.016 mi
Registration #12	2015-11-23	89.470 mi
Registration #13	2015-11-23	89.470 mi
Registration #14	2016-11-16	96.592 mi
Registration #15	2017-11-02	103.123 mi
Registration #16	2017-11-06	103.258 mi
Registration #17	2018-05-22	111.377 mi
Registration #18	2018-05-22	111.377 mi
Registration #19	2018-05-22	111.377 mi
Registration #20	2018-05-22	111.377 mi
Registration #21	2018-05-22	111.377 mi
Registration #22	2018-05-22	111.377 mi
Registration #23	2018-05-22	111.377 mi
Registration #24	2018-05-22	111.377 mi
Registration #25	2018-05-22	111.377 mi
Registration #26	2018-05-22	111.377 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1735 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27296030175281