





report date: 2024-03-29

General information

Make	AUDI
Model	A3 TFSI SPORT
Colour	Black
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/13



MM57CGK report date: 2024-03-29

Internet history

	-	٠	B43.4	,	1
_	ш	L	ΙV		ж,

ciitiy 1	
Date	2021-01-27
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-12-05
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	21
Total items failed	5

MOT #18	2023-11-24 16:35
MOT test number	524281259132
Result	✓ Passed
Next expiry date	2024-12-05

MOT #17	2022-12-02 12:28
MOT test number	714449088205
Result	✓ Passed
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #16	2021-12-06 10:00
MOT test number	339235258545
Result	✓ Passed
MOT #15	2020-06-08 11:27
MOT test number	385025118058
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front Coil spring corroded (5.3.1 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13

MOT test number

547988256147

Result

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge nail in tyre (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT test number

Foult

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge nail in tyre (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #11
 2017-06-02 16:26

 MOT test number
 251420870539

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10	2017-06-02 09:09
MOT test number	742648854622
Result	× Failed
Fail Offside Rear coil spring broken (2.4.C.1a)	

MOT #9	2016-06-03 15:54
MOT test number	239502711200
Result	✓ Passed
MOT #8	2015-06-17 14:51
MOT test number	296638365123
Result	✓ Passed
Notice Front number plate cracked	

MOT #7	2014-07-22 15:23
MOT test number	419623504204
Result	✓ Passed
MOT #6	2014-07-22 09:55
MOT test number	926553804202
Result	X Failed
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2013-06-28 12:28
MOT test number	957189073193
Result	✓ Passed
Notice Offside rear tyre cut in tread	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4	2013-06-27 16:44
MOT test number	438368373120
Result	× Failed
Notice Under-trays fitted obscuring some underside components	
Notice Nearside rear tyre perished	
Fail Brakes imbalanced across an axle (3.7.B.5b)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Oil leak	
Notice Offside front tyre feathered on outter edge	
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to rea (4.1.D.1a)	ach the ply or cords
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

7-20 14:46 02802258
12802258
22002230
✓ Passed
7-12 15:44
63291185
✓ Passed
05 10:33
05501015
✓ Passed
/

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	biotom,
UWNEI	nisioiv

e when mistery	
For how long did the current and previous owner(s) have this AUDI? How many owners Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-01-15
Last registration	2023-11-24
Complete history	See info



Registration #1	2008-01-15	21 mi
Registration #2	2011-01-05	20.018 mi
Registration #3	2011-07-12	22.215 mi
Registration #4	2012-07-20	36.917 mi
Registration #5	2013-06-27	45.912 mi
Registration #6	2013-06-28	45.939 mi
Registration #7	2014-07-22	55.518 mi
Registration #8	2014-07-22	55.518 mi
Registration #9	2015-06-17	63.362 mi
Registration #10	2016-06-03	69.118 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777-es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4214 mm
Wheel base	2578 mm
Max. allowed weight	1820 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number Carcheck.co.uk	CAX 019612 page 13/13