




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 COMBI CDTI BITURBO S/S
Colour	Blue
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	49.6 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-12-09
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-12
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	14
Total items failed	3

MOT #9	2024-01-29 13:33
MOT test number	784962281906
Result	✓ Passed
Next expiry date	2025-02-12
Advice	Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #8	2024-01-29 13:33
MOT test number	726874803924
Result	✗ Failed
Advice	Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Pass with rectification	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Pass with rectification	Stop lamp(s) not working eye level (4.3.1 (a) (ii))

**MOT #7** 2023-02-13 13:37**MOT test number** 501875533135**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Damage to o/s/f outer sill**MOT #6** 2022-10-10 08:40**MOT test number** 997434989477**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Upper Shock absorbers has a slightly worn bush BORDERLINE (5.3.2 (c))**Advice** Nearside Front Lower Suspension arm ball joint has slight play BORDERLINE (5.3.4 (a) (i))**MOT #5** 2021-04-22 08:49**MOT test number** 844357325768**Result** ✓ Passed**MOT #4** 2020-02-01 14:19**MOT test number** 634744561888**Result** ✓ Passed**MOT #3** 2019-09-04 13:45**MOT test number** 625922715791**Result** ✓ Passed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #2** 2019-03-11 13:49**MOT test number** 368250607669**Result** ✓ Passed



MOT #1	2018-09-12 10:00
MOT test number	174886373078
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
12 February 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history


For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-29
Current registration	 XXXXXX
Plate since	2020-01-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-09-07
Last registration	2024-01-29
Complete history	See info



Registration #1	2017-09-07	6 mi
Registration #2	2018-09-12	67.852 mi
Registration #3	2019-03-11	91.051 mi
Registration #4	2019-09-04	120.037 mi
Registration #5	2020-02-01	135.584 mi
Registration #6	2021-04-22	152.209 mi
Registration #7	2022-05-20	161.277 mi
Registration #8	2023-05-20	161.277 mi
Registration #9	2023-05-20	161.277 mi
Registration #10	2023-05-20	161.277 mi
Registration #11	2024-01-29	161.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1842 kg
Max. allowed weight	3020 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	R9M MH - C199198LQI