





report date: 2024-03-28

## General information

| Make                | BMW              |
|---------------------|------------------|
| Model               | 1 SERIES 116D SE |
| Colour              | White            |
| Year of manufacture | 2017             |
| Top speed           | 124 mph          |
| 0 - 60 mph          | 10.3 seconds     |
| Gearbox             | 6 speed Manual   |

## Engine & fuel consumption

| Power                   | 114 BHP             |  |
|-------------------------|---------------------|--|
| Max. torque             | 270 Nm at 1.750 rpm |  |
| Engine capacity         | 1.496 сс            |  |
| Cylinders               | 3                   |  |
| Fuel type               | Diesel              |  |
| Consumption city        | 68.9 mpg            |  |
| Consumption extra urban | 85.6 mpg            |  |
| Consumption combined    | 78.5 mpg            |  |
| CO2 emission            | 94 g/km             |  |
| CO2 label               | A                   |  |



CarCheck.co.uk page 1/11



## Internet history

## Entry 2


Date 2023-10-20

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date    | 2025-05-22 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 2          |
| Total advice items | 11         |
| Total items failed | 0          |

| MOT #6   |        | 2024-04-25 11:02 |
|--|--------|------------------|
| MOT test   | number | 923938784375     |
| Result   |        | ✓ Passed         |
| Next expiry date 2025-05-22  |        |                  |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |        |                  |
| Advice Front Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))            |        |                  |
| Minor Offside Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))     |        |                  |

| MOT #5  | 2024-04-24 13:05               |
|---|--------------------------------|
| MOT test number   | 210135091437                   |
| Result  | <b>X</b> Failed                |
| MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep end (5.2.3 (d) (i)) | ough to reach the ply or cords |
| Minor Offside Stop lamp(s) lens defective which has no effect on emitted lig              | ht (4.3.1 (b) (i))             |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply                 | or cords (5.2.3 (d) (i))       |
| Advice Front Brake disc worn, but not excessively offside and nearside (1.1.              | 14 (a) (i))                    |

| MOT #4                  | 2023-05-23 11:20   |
|-------------------------|--|
| MOT test number         | 656558099674   |
| Result                  | <b>✓</b> Passed  |
| Advice Brake disc worn, | pitted or scored, but not seriously weakened all (1.1.14 (a) (ii)) |

CarCheck.co.uk page 3/11



YC67XMS

report date: 2024-03-28

MOT #3 2021-10-25 11:44

**MOT test number** 471953872046

MOT #2 2020-10-23 15:08

**MOT test number** 790891678490

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2020-10-23 11:08

**MOT test number** 559521547630

**Result** X Failed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/11



## Tax & MOT check



| Tax status       | Valid until 1 December |
|------------------|------------------------|
| Days left        | 215                    |
| MOT expiry date  | 22 May 2025            |
| Full MOT history | See MOT history        |

### Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | E          |
| First licence fee (12 months)                        | £ 165,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 185,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 5/11



YC67XMS

report date: 2024-03-28

## Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| ·  |           |     |
|--|-----------|-----|
| For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>have the current and the full report have the current and the full report have the current and the full report have the current and previous owner(s) have this BMW? How many owners did not be all the current and previous owner(s) have the current and current and previous owner(s) have the current and current a</u> |           | ve? |
| ********   |           |     |
|  |           |     |
| ***************************************  |           |     |
| ***************************************  |           |     |
|  |           |     |
| ***************************************  |           |     |
|  |           |     |
|  | More info | >   |
| Plate changes  |           |     |
| See in this check if this BMW had different number plates.   |           |     |
| Number of plates   |           | ,   |
| Current registration   | UK UK     |     |
| Plate since  |           |     |
| Current registration   | UK UK     |     |
| Plate since  |           |     |
|  | More info | >   |
|  |           |     |

CarCheck.co.uk page 8/11



**YC67XMS** 

report date: 2024-03-28

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 9/11



## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 8          |
| First mileage registration | 2017-11-16 |
| Last registration          | 2024-04-25 |
| Complete history           | See info   |



| Registration #1 | 2017-11-16 | 29 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2020-10-23 | 43.233 mi |
| Registration #3 | 2020-10-23 | 43.234 mi |
| Registration #4 | 2021-10-25 | 45.561 mi |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 11.777 es |
| Registration #7 |            | 11.777 es |
| Registration #8 |            |           |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 50567 |                  |
| 50569 |                  |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 91%             |
| Children       | 83%             |
| Pedestrian     | 63%             |
| Safety systems | 86%             |
| Overall rating | 83%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1765 mm |
|---------------------|---------|
| Height              | 1421 mm |
| Length              | 4329 mm |
| Wheel base          | 2690 mm |
| Kerb weight         | 1320 kg |
| Max. allowed weight | 1885 kg |

## Additional information

| Fuel tank capacity                | 52 I             |           |
|-----------------------------------|------------------|-----------|
| Fuel delivery                     | Direct Injection |           |
| Number of doors                   | 5                |           |
| Number of seats<br>CarCheck.co.uk | 5 pa             | nge 11/11 |

Number of axles 2

**Engine number** 36269896