




report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I ROADSTER SE
Colour	Blue
Year of manufacture	2009
Top speed	135 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	188 Nm at 5.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-19
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-04
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	32
Total items failed	3

MOT #18	2024-03-05 16:23
MOT test number	449647160368
Result	✓ Passed
Next expiry date	2025-03-04
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
Advice	Nearside Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

MOT #17	2023-02-20 15:32
MOT test number	434661718226
Result	✓ Passed
Advice	Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive Inner/outer sills and floor (7.1.1 (a) (i))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive Inner/outer sills and floor (7.1.1 (a) (i))

MOT #16	2022-02-21 11:54
MOT test number	652903334443
Result	✓ Passed

**MOT #15** 2022-02-16 15:38**MOT test number** 492738974911**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))**MOT #14** 2021-12-08 12:31**MOT test number** 338023139912**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**MOT #13** 2020-12-29 16:03**MOT test number** 314811419565**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Oil leak, but not excessive diff (8.4.1 (a) (i))

**MOT #12** 2019-11-29 13:00**MOT test number** 417338010841**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**MOT #11** 2019-11-27 11:39**MOT test number** 226063877034**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-11-28 14:12**MOT test number** 260768496730**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin to limit (1.1.13 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin to limit (1.1.13 (a) (ii))**MOT #9** 2017-10-31 15:39**MOT test number** 186288611029**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin to limit (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2016-11-04 10:51**MOT test number** 810787000139**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear tyre wearing low**MOT #7** 2016-11-01 10:40**MOT test number** 653672150603**Result** ✗ Failed**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear tyre wearing low**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2015-11-03 14:31**MOT test number** 302201441663**Result** ✓ Passed**MOT #5** 2015-02-02 17:02**MOT test number** 667173035099**Result** ✓ Passed**MOT #4** 2015-02-02 17:02**MOT test number** 708273535033**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2014-05-22 12:27**MOT test number** 238622644478**Result** ✓ Passed



MOT #2	2013-05-22 14:01
MOT test number	588142843151
Result	✓ Passed

MOT #1	2012-05-30 09:19
MOT test number	339071752133
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
4 March 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	4 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-06-30
Last registration	2024-03-05
Complete history	<a href="#">See info</a>



Registration #1	2009-06-30	14 mi
Registration #2	2012-05-30	33.375 mi
Registration #3	2013-05-22	44.017 mi
Registration #4	2014-05-22	50.804 mi
Registration #5	2015-02-02	53.718 mi
Registration #6	2015-11-03	70.415 mi
Registration #7	2016-11-01	77.307 mi
Registration #8	2016-11-04	77.317 mi
Registration #9	2017-10-31	84.368 mi
Registration #10	2018-11-28	92.756 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	4020 mm
Wheel base	2330 mm
Kerb weight	1165 kg
Max. allowed weight	1375 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF 10796099