



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 LIFE TDI
Colour	Grey
Year of manufacture	2016
Top speed	106 mph
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-14
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-12
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	16
Total items failed	7

MOT #13	2024-04-04 12:02
MOT test number	183366881208
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12	2024-04-04 12:02
MOT test number	951118514618
Result	✗ Failed
Pass with rectification	Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Pass with rectification	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2024-03-29 17:03

MOT test number

203015513550

Result**✗ Failed****Advice** T p m light on**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play insert excess play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2024-03-28 14:25

MOT test number

134256226623

Result**✗ Failed****Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Macpherson strut attachment bracket/mounting likely to become detached top mounting / bearing collapsed (5.3.3 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9**

2023-04-13 10:12

MOT test number

293650164745

Result**✓ Passed****MOT #8**

2022-04-11 07:11

MOT test number

474433943856

Result**✓ Passed**

**MOT #7** 2021-03-23 10:38**MOT test number** 270504841997**Result** ✓ Passed

Minor Front Windscreen damaged but not adversely affecting driver's view Multiple stone chips (3.2 (a) (i))

MOT #6 2020-03-25 12:52**MOT test number** 202950401793**Result** ✓ Passed**MOT #5** 2020-03-19 15:05**MOT test number** 348505476563**Result** ✗ Failed

Fail Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Minor Windscreen damaged but not adversely affecting driver's view stone chips (3.2 (a) (i))

MOT #4 2019-07-15 10:30**MOT test number** 675863452952**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge on outer edge 205 55 16 (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2019-07-15 09:06**MOT test number** 852382789284**Result** ✗ Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on outer edge 205 55 16 (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #2	2018-07-16 14:04
MOT test number	416859297960
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1	2017-07-18 14:04
MOT test number	922828717088
Result	✓ Passed
Advice	Tyre worn close to the legal limit both front (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
12 April 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	GL16KYG
Plate since	2019-06-29
Current registration	GL16KYG
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2016-04-27
Last registration	2024-04-04
Complete history	See info



Registration #1	2016-04-27	28 mi
Registration #2	2017-07-18	25.248 mi
Registration #3	2018-07-16	75.488 mi
Registration #4	2019-07-15	108.646 mi
Registration #5	2019-07-15	108.646 mi
Registration #6	2020-03-19	132.412 mi
Registration #7	2020-03-25	132.502 mi
Registration #8	2021-03-23	142.779 mi
Registration #9	2022-03-23	152.779 mi
Registration #10	2022-03-23	152.779 mi
Registration #11	2022-03-23	152.779 mi
Registration #12	2022-03-23	152.779 mi
Registration #13	2022-03-23	152.779 mi
Registration #14	2022-03-23	152.779 mi
Registration #15	2022-03-23	152.779 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1793 mm
Height	1831 mm
Length	4878 mm
Wheel base	3006 mm
Kerb weight	577 kg
Max. allowed weight	2360 kg

Additional information

Fuel tank capacity	60 l
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	DFSD075319