



PEUGEOT



VN5IYVO

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 LX
Colour	Grey
Year of manufacture	2002
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-23
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-01-14
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	46
Total items failed	16

MOT #24	2022-01-15 13:56
MOT test number	826563366032
Result	✓ Passed
Next expiry date	2023-01-14
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #23	2022-01-15 13:56
MOT test number	986959686035
Result	✗ Failed
Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22**

2021-01-11 09:27

MOT test number

237941967671

Result

✓ Passed

- Advice** Nearside Front Upper Suspension component mounting prescribed area is corroded but not considered excessive spring mount (5.3.6 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Drivers seat has slight movement in runners
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21

2020-01-10 12:23

MOT test number

912110383851

Result

✓ Passed

- Advice** Parking brake has little reserve travel
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both bushes (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both bushes (5.3.4 (a) (i))

**MOT #20**

2019-01-14 15:43

MOT test number

163690015630

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases x3 (6.1.2 (a))
- Minor** Anti-roll bar linkage ball joint dust cover severely deteriorated both front (5.3.4 (b) (i))
- Advice** Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Indicator switch faulty (4.4.2 (a) (i))
- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Coil spring corroded both front (5.3.1 (b) (i))

MOT #19

2019-01-14 09:24

MOT test number

762429820930

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Anti-roll bar linkage ball joint dust cover severely deteriorated both front (5.3.4 (b) (i))
- Fail** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))
- Advice** Exhaust mounting defective (6.1.2 (a))
- Minor** Indicator switch faulty (4.4.2 (a) (i))
- Advice** Coil spring corroded both front (5.3.1 (b) (i))
- Advice** Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))
- Advice** Exhaust has a minor leak of exhaust gases x3 (6.1.2 (a))



MOT #182018-01-15 16:21

MOT test number325396585486

Result

✓ Passed

- Advice

Offside Front Tyre worn close to the legal limit bold on edges (4.1.E.1)
- Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice

Aux belt deteriorated
- Advice

Nearside Front Tyre worn close to the legal limit bold on edges (4.1.E.1)
- Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice

Oil leak

**MOT #17**

2018-01-13 09:28

MOT test number

663397920386

Result**✗ Failed**

Fail Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Nearside Front Tyre worn close to the legal limit bold on edges (4.1.E.1)

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

Fail Brake load sensing valve seized (3.6.E.3)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

Advice Offside Front Tyre worn close to the legal limit bold on edges (4.1.E.1)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Oil leak

Advice Aux belt deteriorated

MOT #16

2017-01-10 15:16

MOT test number

410463900010

Result**✓ Passed**

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #15** 2017-01-09 13:28**MOT test number** 325734289610**Result** ✗ Failed**Fail** Nearside Front Mechanical brake component has restricted free movement (3.5.1k)**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Brake load sensing valve seized (3.6.E.3)**MOT #14** 2016-01-11 11:01**MOT test number** 161234392971**Result** ✓ Passed**MOT #13** 2016-01-11 11:01**MOT test number** 408513085466**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #12** 2015-01-07 11:17**MOT test number** 139277505078**Result** ✓ Passed

**MOT #11** 2015-01-07 11:17**MOT test number** 349587905048**Result** ✗ Failed

Pass with rectification Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Pass with rectification Offside rear brake binding (3.7.B.1)

MOT #10 2014-01-06 10:41**MOT test number** 865096204068**Result** ✓ Passed**MOT #9** 2012-12-17 10:54**MOT test number** 949352152349**Result** ✓ Passed**MOT #8** 2012-01-05 10:42**MOT test number** 358645602007**Result** ✓ Passed**MOT #7** 2011-01-13 11:33**MOT test number** 267563111022**Result** ✓ Passed**MOT #6** 2010-01-07 11:04**MOT test number** 202567200068**Result** ✓ Passed

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #5 2009-01-08 12:02**MOT test number** 994918509060**Result** ✓ Passed



MOT #4	2008-01-09 10:34
MOT test number	652619508022
Result	✓ Passed

MOT #3	2008-01-09 10:34
MOT test number	821669308030
Result	✗ Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2	2007-01-08 12:48
MOT test number	164488007462
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #1	2006-01-09 14:04
MOT test number	580939606095
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 July 2022

X

MOT

Expired:
14 January 2023

Tax status	Expired at 1 July 2022
Days left	667 days too late
MOT expiry date	14 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 VN51YVO
Plate since	2024-03-28
Current registration	 VN51YVO
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-01-11
Last registration	2022-01-15
Complete history	See info



Registration #1	2002-01-11	20 mi
Registration #2	2006-01-09	22.105 mi
Registration #3	2007-01-08	27.458 mi
Registration #4	2008-01-09	31.814 mi
Registration #5	2009-01-08	35.899 mi
Registration #6	2010-01-07	38.288 mi
Registration #7	2011-01-13	39.696 mi
Registration #8	2012-01-05	42.703 mi
Registration #9	2012-12-17	44.752 mi
Registration #10	2014-01-06	46.474 mi
Registration #11	2015-01-07	48.256 mi
Registration #12	2016-01-11	51.194 mi
Registration #13	2016-01-11	51.194 mi
Registration #14	2016-01-11	51.194 mi
Registration #15	2016-01-11	51.194 mi
Registration #16	2016-01-11	51.194 mi
Registration #17	2016-01-11	51.194 mi
Registration #18	2016-01-11	51.194 mi
Registration #19	2016-01-11	51.194 mi
Registration #20	2016-01-11	51.194 mi
Registration #21	2016-01-11	51.194 mi
Registration #22	2016-01-11	51.194 mi
Registration #23	2016-01-11	51.194 mi
Registration #24	2016-01-11	51.194 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	FSC43814790