





### General information

Make B	BMW
Model 7	730 730D M SPORT
Colour	Grey
Year of manufacture 2	2014
Top speed 1	155 mph
<b>0 - 60 mph</b> 6	6.1 seconds
Gearbox 8	3 speed automatic

### Engine & fuel consumption

Power	258 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F







## Internet history

Entry 1	
Date	2021-09-23
Pictures	25
Listing price	View report









source: yesauto.com





# MOT history

MOT expiry date	2024-03-15
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	21
Total items failed	2

MOT #11	2023-03-07 12:43
MOT test number	268493739672
Result	✓ Passed
Next expiry date	2024-03-15
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front number plate damaged	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear number plate cracked	

MOT #10	2022-03-04 08:48
MOT test number	140735560818
Result	✓ Passed

МОТ #9	202	1-03-12 11:29
MOT test	number 6	45431168376
Result		✓ Passed
Advice	Service brake fluctuating, but not excessively both rear (1.2.1 (e))	
Minor	Windscreen damaged but not adversely affecting driver's view outside zone A (3.2 (a)	(i))





MOT #8	20	021-03-11 15:48
MOT test	number	983120440214
Result		🗙 Failed
Advice	Service brake fluctuating, but not excessively both rear (1.2.1 (e))	
Minor	Windscreen damaged but not adversely affecting driver's view outside zone A (3.2 (a	a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
MAJOR	Nearside Front Service brake excessively fluctuating (1.2.1 (e))	
DANGE	<b>ROUS</b> Nearside Rear Road wheel fractured (5.2.2 (a))	

MOT #7	2020-03-10 12:18
MOT test	number 597829089395
Result	✓ Passed
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6	2020-	03-04 13:19
MOT test	number 71	5554237856
Result		🗙 Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Service brake fluctuating, but not excessively both rear (1.2.1 (e))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))	
MAJOR	Offside Front Suspension arm ball joint excessively worn lower (5.3.4 (a) (i))	
Advice	Service brake fluctuating, but not excessively both front (1.2.1 (e))	
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))	





MOT #5	2019-03-12 12:38
MOT test number	643949511208
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MOT #4	2018-03-16 10:23
MOT test number	904099828243
Result	✓ Passed
MOT #3	2018-03-14 13:00
MOT test number	672982002712
Result	× Failed
Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)	
MOT #2	2017-03-13 12:22
MOT test number	898589488045
Result	✓ Passed
MOT #1	2017-03-13 12:22
MOT test number	436734508235
Result	🗙 Failed





Tax & MOT check

✓ Taxed	X MOT	
Tax due: 1 July 2024	Expired: 15 March 2024	
Tax status	Valid until 1 July	
Days left	62	
MOT expiry date	15 March 2024	
Full MOT history	See MOT history	

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second s	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
************	
********	
*******	
*************	
********	
	More info >
Plate changes	
See in this check if this BMW had different number plates	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-13
Last registration	2023-03-07
Complete history	See info



Registration #1	2014-03-13	10 mi
Registration #2	2017-03-13	24.191 mi
Registration #3	2017-03-13	24.191 mi
Registration #4	2018-03-14	36.058 mi
Registration #5	2018-03-16	36.099 mi
Registration #6	2019-03-12	45.734 mi
Registration #7	2020-03-04	54.251 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		11.117 mi





## Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	1902 mm
Height	1471 mm
Length	5079 mm
Wheel base	3070 mm
Kerb weight	1840 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12