



A059PNE

report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO GLS PLUS
Colour	Orange
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	86 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-04
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #13 2023-06-01 08:23**MOT test number** 587372870658**Result** ✓ Passed**Next expiry date** 2024-06-04**Advice** Rear Suspension arm corroded but not seriously weakened AXLE (5.3.3 (b) (i))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive
Near and Offside sills (5.3.6 (a) (i))**Advice** Rear Service brake binding but not excessively Near and Offside (1.2.1 (f))**Minor** Windscreen wiper blade defective Near and Offside smearing (3.4 (b) (i))**MOT #12** 2022-05-25 08:52**MOT test number** 370788122934**Result** ✓ Passed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #11** 2021-06-05 10:14**MOT test number** 222937277735**Result** ✓ Passed

**MOT #10**

2021-06-03 11:16

MOT test number

808445998496

Result**✗ Failed**

- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Nail in tyre
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Upper Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))

MOT #9

2019-10-29 10:47

MOT test number

101260580524

Result**✓ Passed**

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2018-10-19 11:26

MOT test number

164774851371

Result**✓ Passed**

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #7** 2018-10-17 10:08**MOT test number** 664363281041**Result** ✗ Failed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2017-11-10 14:21**MOT test number** 807518535112**Result** ✓ Passed**MOT #5** 2016-11-18 14:47**MOT test number** 332627083419**Result** ✓ Passed**Advice** Offside Rear Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #4** 2015-11-02 13:55**MOT test number** 799387774131**Result** ✓ Passed**MOT #3** 2014-11-04 14:34**MOT test number** 197308004318**Result** ✓ Passed**MOT #2** 2013-11-11 10:55**MOT test number** 437045913327**Result** ✓ Passed



MOT #1	2012-11-05 13:29
MOT test number	869830612380
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
4 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	4 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-11-18
Last registration	2023-06-01
Complete history	See info



Registration #1	2009-11-18	20 mi
Registration #2	2012-11-05	12.284 mi
Registration #3	2013-11-11	16.189 mi
Registration #4	2014-11-04	19.623 mi
Registration #5	2015-11-02	22.827 mi
Registration #6	2016-11-18	28.336 mi
Registration #7	2017-11-10	34.724 mi
Registration #8	2018-10-17	39.324 mi
Registration #9	2019-10-20	44.337 mi
Registration #10	2020-10-20	49.350 mi
Registration #11	2021-10-20	54.363 mi
Registration #12	2022-10-20	59.376 mi
Registration #13	2023-10-20	64.389 mi
Registration #14	2024-10-20	69.402 mi
Registration #15	2025-10-20	74.415 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3715 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1045882