





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Blue
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-21

Pictures 31

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-26
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #10	2023-11-20 12:03
MOT test number	336191834114
Result	✓ Passed
Next expiry date	2024-11-26

MOT #9	2022-11-02 16:33
MOT test number	169204485553
Result	✓ Passed

MOT #8	2022-11-02 09:44
MOT test number	615591893702
Result	× Failed
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #7		2021-11-23 17:17
MOT test	number	642372052328
Result		✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weake	ned inner edge (1.1.14 (a)

CarCheck.co.uk page 3/12



MOT #6 2020-11-27 09:38

MOT test number 930172589583

Result ✓ Passed

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Integral body structure is corroded but structural rigidity is not significantly reduced Sill

(6.1.1 (c) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))

MOT #5 2019-10-26 09:34

MOT test number 596806953131

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-11-19 14:55

MOT test number 173204085390

Result ✓ Passed

MOT #3 2018-11-19 14:55

MOT test number 601826752962

Result X Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/12



MOT #2	2017-10-02 08:40
MOT test number	101151242825
Result	✓ Passed
MOT #1	2016-10-03 08:45
MOT test number	512688387851
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	26 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



KY63GAO

report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	AIR AIR
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-30
Last registration	2023-11-20
Complete history	See info



Registration #1	2013-09-30	20 mi
Registration #2	2016-10-03	32.047 mi
Registration #3	2017-10-02	48.936 mi
Registration #4	2018-11-19	59.407 mi
Registration #5	2018-11-19	59.407 mi
Registration #6	2019-10-26	71.229 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 ms
Registration #12		n

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12