





General information

| Make | RENAULT |
|---------------------|-------------------------------|
| Model | TRAFIC SL27 SPORT DCI S/R P/V |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 99 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 115 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 1.500 rpm |
| Engine capacity | 1.996 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.0 mpg |
| Consumption extra urban | 43.5 mpg |
| Consumption combined | 37.7 mpg |
| CO2 emission | 198 g/km |
| CO2 label | J |



Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2022-03-12 |
| Pictures | 11 |
| Listing price | View report |



source: yesauto.com

| Entry 1 | |
|---------------|-------------|
| Date | 2022-03-08 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk









MOT history

| MOT expiry date | 2025-03-10 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 17 |
| Total items failed | 7 |

| MOT #11 | 2024-03-07 09:44 |
|---|------------------|
| MOT test number | 899229449541 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-10 |
| Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |

| MOT #10 | 2023-03-06 09:52 |
|-----------------|------------------|
| MOT test number | 476770515950 |
| Result | ✓ Passed |
| | |
| МОТ #9 | 2022-03-11 10:46 |

| | 9. 19 |
|-----------------|--------------|
| MOT test number | 216876777874 |
| Result | ✓ Passed |



| MOT #8 | 2022-03-09 10:07 |
|---|----------------------|
| MOT test number | 175076327008 |
| Result | 🗙 Failed |
| Fail Hazard warning lamps inoperative ALL LAMPS INOP (4.4.1 (e)) | |
| Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer pre of dirt REPAIRED WITH TIE WRAP, REQUIRES CORRECT RETAINING CLIP (6.1.7 (g) (ii)) | events the ingress |
| Fail Brake performance not tested DUE TO INACCURATE READINGS FROM CONTAMINAT | TED DISC (1.2.1 (g)) |
| Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Fail Offside Front Inner Brake disc contaminated INNER SIDE OF BRAKE DISC CONTAMI GREASE, REQUIRES CLEANING (1.1.14 (b)) | NATED WITH CV |

| MOT #7 | 2 | 021-11-13 10:06 |
|----------|--|-----------------|
| MOT test | number | 162611623367 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 | (a) (ii)) |

| МОТ #6 | 2021-11-13 10:06 | |
|---|--|--|
| MOT test number | 105658472497 | |
| Result | × Failed | |
| Advice Offside Rear Tyr | e worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Pass with rectification Offside Front Drive shaft joint constant velocity boot split or insecure, no longer | | |
| prevents the ingress of dirt | (6.1.7 (g) (ii)) | |
| Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Advice Offside Front Tra | ack rod end ball joint has slight play (2.1.3 (b) (i)) | |

| MOT #5 | 2020-11-06 16:14 |
|-----------------|------------------|
| MOT test number | 931236601614 |
| Result | ✓ Passed |





| MOT #4 | 2019-11-27 13:15 |
|---|------------------|
| MOT test number | 355822084308 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2018-09-12 09:06 |
| MOT test number | 139806118410 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e)) | |
| Advice Front antiroll bar d bushes worn | |
| Minor Front Windscreen wiper blade defective worn screen dirty (3.4 (b) (i)) | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (| (ii)) |

| MOT #2 | | 2017-08-29 13:32 |
|-----------------------|---|------------------|
| MOT test | number | 898626503230 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) | |
| Advice rubber (2.4 | Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excess 4.G.2) | sive movement D |

| MOT #1 | 2017-08-29 08:23 |
|---|---------------------|
| MOT test number | 989938895723 |
| Result | 🗙 Failed |
| Fail Registration plate deteriorated damaged (6.3.1d) | |
| Advice Rear Brake pad(s) wearing thin (3.5.1g) | |
| Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to rea (4.1.D.1a) | ch the ply or cords |
| Advice Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in exrubber (2.4.G.2) | xcessive movement D |
| Advice Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1) | |



Tax & MOT check

| Tax due: 1 October 2024 | √ axed | Expires: 10 March 2025 | ✓ мот |
|-----------------------------------|-----------|----------------------------------|------------------------|
| Tax status | | | Valid until 1 October |
| Days left | | | 154 |
| MOT expiry date | | | 10 March 2025 |
| Full MOT history | | | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********** | |
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2014-09-17 |
| Last registration | 2024-03-07 |
| Complete history | See info |



| Registration #1 | 2014-09-17 | 6 mi |
|------------------|------------|--|
| Registration #2 | 2017-08-29 | 50.452 mi |
| Registration #3 | 2017-08-29 | 50.452 mi |
| Registration #4 | 2018-09-12 | 73.986 mi |
| Registration #5 | 2019-11-27 | 89.588 mi |
| Registration #6 | 2020-11-06 | 96.048 mi |
| Registration #7 | 2021-11-13 | 102.406 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Devictuation #11 | | |
| Registration #11 | | 11.777 est |
| Registration #12 | | 11.777 es |
| | | 01,000 est 01,000 est 01,000 est |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

Number of doors

Number of seats

Number of axles CarCheck.co.uk

| NCAP rating | ***** |
|----------------|-----------------|
| Adult | 58% |
| Children | 79% |
| Pedestrian | 28% |
| Safety systems | 14% |
| Overall rating | 51% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|------------------|
| Width | 1904 mm |
| Height | 1944 mm |
| Length | 4784 mm |
| Kerb weight | 1710 kg |
| Max. allowed weight | 2790 kg |
| Additional information | |
| Fuel tank capacity | 90 |
| Fuel delivery | Direct Injection |

3

3

2

Engine number

C161336