





General information

| Make | CITROEN |
|---------------------|--|
| Model | DISPATCH M 1000 ENTERPRISE BLUEHDI S/S |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 99 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 113 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 137 g/km |
| CO2 label | E |







Internet history

Entry 1

Date Pictures 2021-09-14

33

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-08-31 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 2 |

| MOT #5 | 2023-08-31 12:50 |
|--|--------------------------------|
| MOT test number | 256851333114 |
| Result | ✓ Passed |
| Next expiry date 2024-08-3 | |
| Minor Offside Front Outer Drive shaft joint constant velocity boot severel | y deteriorated (6.1.7 (g) (i)) |

| MOT #4 | 2023-08-31 10:24 |
|--|--------------------|
| MOT test number | 422997552944 |
| Result | 🗙 Failed |
| Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorate | ed (6.1.7 (g) (i)) |
| Fail Offside Front Seat belt not functioning as intended Webbing twisted. (7.1.2 (c)) | |

| MOT #3 | 2022-08-30 12:59 |
|--|-------------------|
| MOT test number | 588610762678 |
| Result | ✓ Passed |
| Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated | d (6.1.7 (g) (i)) |





| MOT #2 | 2022-08-26 13:22 |
|------------------------------------|--|
| MOT test number | 805980598617 |
| Result | × Failed |
| Advice Nearside Rear Tyre worn | close to legal limit/worn on edge (5.2.3 (e)) |
| Minor Offside Front Drive shaft jo | pint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Advice Nearside Rear Nail in tyre | 3 |
| Advice Offside Rear Tyre slightly | damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Fail Nearside Rear Tyre has a bull | lge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |
| | |

| MOT #1 | 2021-08-19 12:45 |
|-----------------|------------------|
| MOT test number | 920666698255 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 September 2024 | ✓ MOT Expires: 31 August 2024 |
|--|--|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 31 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|----------|--------------|
| Date | | |
| Category | | Lawer |
| Туре | (******* | |
| Damage 2 | | AMPLE |
| Damage 2 | | E CONTRACTOR |
| Date | | |
| Category | | AMP |
| Туре | | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 11.111 |
| Average private trade value | 4 10 200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********* | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |

More info \rightarrow





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow



CN68GLV report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-09-01 |
| Last registration | 2023-08-31 |
| Complete history | See info |



| Registration #1 | 2018-09-01 | 19 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-08-19 | 48.100 mi |
| Registration #3 | | 11.777 mi |
| Registration #4 | 2022-08-26 | 58.453 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |

More info >



Dimensions & weight

| Width | 2204 mm |
|---------------------|---------|
| Height | 1899 mm |
| Length | 4959 mm |
| Kerb weight | 1533 kg |
| Max. allowed weight | 2660 kg |
| | |

Additional information

| Fuel tank capacity | 70 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 6 |
| Number of seats | 3 |
| Engine number | JCAP0004806 |