



General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI CC DSG
Colour	Black
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	8.1 mpg
Consumption extra urban	5.1 mpg
Consumption combined	6.2 mpg
CO2 emission	163 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-09-02
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-12
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	32
Total items failed	2

MOT #15	2024-01-13 13:35
MOT test number	137575964883
Result	✓ Passed
Next expiry date	2025-01-12
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2023-01-07 08:19
MOT test number	893459557164
Result	✓ Passed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2354018y95 3mm (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2023-01-04 16:56

**MOT test number**

607477264801

**Result**

✗ Failed

**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2354018y95 3mm (5.2.3 (e))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2022-01-06 10:47

**MOT test number**

577500775861

**Result**

✓ Passed

**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11**

2020-12-30 12:01

**MOT test number**

818698981132

**Result**

✓ Passed

**MOT #10**

2020-01-02 17:40

**MOT test number**

517074652029

**Result**

✓ Passed

**MOT #9** 2019-01-04 12:16**MOT test number** 304968754679**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #8** 2018-01-05 11:24**MOT test number** 251585727110**Result** ✓ Passed

- Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #7** 2017-01-07 16:30**MOT test number** 173209993412**Result** ✓ Passed

- Advice** Central Lower engine mounting deteriorated, but not resulting in excessive movement slight - ( sub frame mounted ) (6.1.D.1a)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened slight (3.5.1i)
- Advice** Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement nearside and offside - both - ( slight - worn ) (2.4.G.2)
- Advice** Front wipers - ( required soon )
- Advice** Rear Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement nearside and offside - both - ( slight movement - worn ) (2.4.G.2)

**MOT #6**

2016-01-04 15:27

**MOT test number**

959756525748

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit PLUS CUT IN SIDE WALL BUT DOES NOT REACH CORDS (4.1.E.1)

**Advice** EMISSIONS NOT DETECTED

**Advice** Brake pad(s) wearing thin REAR PADS (3.5.1g)

**Advice** REAR SPRINGS UNABLE TO FULLY INSPECT DUE TO ACCESS

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Brake disc worn, pitted or scored, but not seriously weakened FRONT DISCS (3.5.1i)

**MOT #5**

2015-01-08 09:35

**MOT test number**

127468705480

**Result**

✓ Passed

**MOT #4**

2014-01-08 12:55

**MOT test number**

428248004042

**Result**

✓ Passed

**Notice** Nail in nearside rear tyre

**Notice** Rear tyres feathered/out of shape

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Nail in offside rear tyre

**Advice** Nearside Front Direction indicator damaged, but still visible from a reasonable distance (1.4.A.2e)

**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #3	2013-06-21 16:59
MOT test number	605072273176
Result	✓ Passed
MOT #2	2012-06-15 11:09
MOT test number	207957062190
Result	✓ Passed
MOT #1	2012-03-02 16:06
MOT test number	779932562011
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

✓

MOT

Expires:  
12 January 2025

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	12 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>KN58NNZ</b>
Plate since	2024-03-29
Current registration	 <b>KN58NNZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-12
Last registration	2024-01-13
Complete history	<a href="#">See info</a>



Registration #1	2008-11-12	8 mi
Registration #2	2012-03-02	38.640 mi
Registration #3	2012-06-15	41.085 mi
Registration #4	2013-06-21	55.965 mi
Registration #5	2014-01-08	61.134 mi
Registration #6	2015-01-08	71.359 mi
Registration #7	2016-01-04	92.666 mi
Registration #8	2017-01-07	100.217 mi
Registration #9	2018-01-05	106.188 mi
Registration #10	2019-01-05	111.217 mi
Registration #11	2019-01-05	111.217 mi
Registration #12	2019-01-05	111.217 mi
Registration #13	2019-01-05	111.217 mi
Registration #14	2019-01-05	111.217 mi
Registration #15	2019-01-05	111.217 mi
Registration #16	2019-01-05	111.217 mi
Registration #17	2019-01-05	111.217 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1485 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	CBA 129434