




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Beige
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	172 Nm at 3.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	30.4 mpg
CO2 emission	222 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-05-26
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-22
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	13
Total items failed	3

MOT #15	2023-10-16 10:29
MOT test number	448678862164
Result	✓ Passed
Next expiry date	2024-10-22
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-10-19 10:59
MOT test number	872734783988
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDE (1.1.14 (a) (ii))

MOT #13	2021-10-23 10:36
MOT test number	975241239468
Result	✓ Passed
Minor	Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
Minor	Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #12** 2020-11-24 09:56**MOT test number** 367117413506**Result** ✓ Passed

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Rear Brake lining(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11 2019-11-07 09:08**MOT test number** 285648249790**Result** ✓ Passed**MOT #10** 2018-11-06 12:14**MOT test number** 615053504056**Result** ✓ Passed**MOT #9** 2017-11-07 10:33**MOT test number** 879044280981**Result** ✓ Passed**MOT #8** 2016-11-01 12:34**MOT test number** 114941496500**Result** ✓ Passed**MOT #7** 2015-11-03 11:56**MOT test number** 672817088421**Result** ✓ Passed

**MOT #6** 2014-12-01 12:27**MOT test number** 798175534319**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2013-10-10 09:12**MOT test number** 288293483212**Result** ✓ Passed**MOT #4** 2012-10-26 17:46**MOT test number** 479640702427**Result** ✓ Passed**MOT #3** 2012-10-22 09:14**MOT test number** 196656092277**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #2** 2011-10-19 14:40**MOT test number** 925932491282**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-10-29 10:45
MOT test number	293822200345
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	22 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LS57EHX
Plate since	2019-06-29
Current registration	 LS57EHX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-10-31
Last registration	2023-10-16
Complete history	See info



Registration #1	2007-10-31	14 mi
Registration #2	2010-10-29	29.542 mi
Registration #3	2011-10-19	39.545 mi
Registration #4	2012-10-22	47.684 mi
Registration #5	2012-10-26	47.684 mi
Registration #6	2013-10-10	55.850 mi
Registration #7	2014-12-01	59.992 mi
Registration #8	2015-11-03	61.180 mi
Registration #9	2016-11-01	62.642 mi
Registration #10	2016-11-01	62.642 mi
Registration #11	2016-11-01	62.642 mi
Registration #12	2016-11-01	62.642 mi
Registration #13	2016-11-01	62.642 mi
Registration #14	2016-11-01	62.642 mi
Registration #15	2016-11-01	62.642 mi
Registration #16	2016-11-01	62.642 mi
Registration #17	2016-11-01	62.642 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1437 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Engine number	AZJ 753509