





report date: 2024-03-29

General information

Make	FORD
Model	FUSION 16V LX
Colour	Blue
Year of manufacture	2003
Top speed	104 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	153 g/km
CO2 label	G



CarCheck.co.uk page 1/17



MOT history

MOT expiry date	2021-01-15
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	83
Total items failed	19

MOT #20		2019-07-16 08:45
MOT test	number	387817575731
Result		✓ Passed
Next expi	ry date	2021-01-15
Advice	Rear exhaust joint blowing slightly	
Advice	O/s/f brake pipe to flexi corroded	
Advice	O/s/f tyre worn on both edges	
Advice	Rear brake pipes to flexis and wheel cylinders corroded	
Advice	O/s/r shock absorber has light misting of oil	
Advice	N/s/f brake pipe to flexi corroded	
Advice	Slight play in n/s/r wheel bearing	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	O/s/f head light lens deteriorated	

CarCheck.co.uk page 2/17



Advice

FE53VAJ report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge and tread splitting (5.2.3 (e))

Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #18

MOT test number

Result

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Rear Brake pipe slightly corroded X2 (3.6.B.2c)

MOT #17 2017-06-21 13:09 690431932746 **MOT** test number Result Failed Fail Nearside Front coil spring broken (2.4.C.1a) Fail Anti-roll bar linkage severely distorted (2.4.G.1) Fail Nearside Front Headlamp aim too low (1.8) Fail Nearside Front Tyre fouling a part of the vehicle (4.1.D.2) **Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c) Fail Rear Exhaust has a major leak of exhaust gases (7.1.2) **Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3) **Advice** Rear Brake pipe slightly corroded X2 (3.6.B.2c)

CarCheck.co.uk page 3/17



FE53VAJ

report date: 2024-03-29

MOT #16 2016-06-29 13:16

MOT test number 920811864551

Result ✓ Passed **Advice** Front Direction indicators slightly discoloured (1.4.A.2f) Advice Rear Brake pipe slightly corroded both sides, (3.6.B.2c) Advice Offside Front Tyre worn close to the legal limit 3 mm, large cracks forming in tread, 195/60/15 (4.1.E.1) Advice Rear coil spring corroded both sides, (2.4.C.1b) Advice Horn raspy Advice Engine cover fitted Advice Offside Front coil spring corroded (2.4.C.1b) Oil leak Advice Advice Nearside Front Tyre worn close to the legal limit 3 mm, (4.1.E.1) Advice Front Brake pipe slightly corroded both sides, (3.6.B.2c) **Advice** O/s wiper blade on the small side

CarCheck.co.uk page 4/17



MOT #15 2016-06-28 13:57

MOT test number 581494163991

Result **X** Failed Advice Offside Front coil spring corroded (2.4.C.1b) Advice O/s wiper blade on the small side Advice Front Brake pipe slightly corroded both sides, (3.6.B.2c) Advice Oil leak Nearside Headlamp aim beam image obviously incorrect image moving up and down, (1.8.A.1b) Fail Advice Nearside Front Tyre worn close to the legal limit 3 mm, (4.1.E.1) Front Direction indicators slightly discoloured (1.4.A.2f) Advice Advice Horn raspy Advice Rear coil spring corroded both sides, (2.4.C.1b) Advice Engine cover fitted Advice Rear Brake pipe slightly corroded both sides, (3.6.B.2c) Advice Offside Front Tyre worn close to the legal limit 3 mm, large cracks forming in tread, 195/60/15 (4.1.E.1) Pass with rectification Windscreen washer provides insufficient washer liquid water (8.2.3)

CarCheck.co.uk page 5/17



MOT #14 2015-06-29 13:40

MOT test number 246110685443 Result ✓ Passed **Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a) Notice Oil leak Advice Rear Brake pipe slightly corroded (3.6.B.2c) Advice Rear coil spring corroded (2.4.C.1b) Notice OSR tyre has small crackes bwtween the tread Advice Front Brake pipe slightly corroded (3.6.B.2c) Advice Nearside Rear Rear wheel bearing has slight play (2.6.2) Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 6/17



Result

FE53VAJ report date: 2024-03-29

X Failed

✓ Passed

MOT #13 2015-06-24 09:45

MOT test number 137185775130

Advice Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)

Advice Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Rear wheel bearing has slight play (2.6.2)

Notice OSR tyre has small crackes bwtween the tread

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Rear coil spring corroded (2.4.C.1b)

Notice Oil leak

Result

Notice

Fail Offside Rear Rear reflector missing (1.5.1a)

Nearside wiper blade torn

MOT #12 2014-06-18 10:53

MOT test number 408659164108

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 7/17



MOT #11 2014-06-14 09:52

MOT test number 577675264159

Result X Failed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)

Advice Nearside Rear wheel bearing has slight play (2.6.2)

Fail Nearside Headlamp insecure (1.7.3)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Offside Headlamp aim too low (1.8)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Front coil spring corroded (2.4.C.1b)

MOT #10 2013-05-25 12:04

MOT test number 889025443139

Result

Passed

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 8/17



MOT #9 2012-06-01 16:49

MOT test number 258513152497

Result ✓ Passed

Notice Offside washer jet partly blocked, but provides sufficient water to clear screen.

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #8 2012-05-31 18:16

MOT test number 218282752483

Result × Failed

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Offside Stop lamp not working (1.2.1b)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Notice Offside washer jet partly blocked, but provides sufficient water to clear screen.

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

MOT #7 2011-08-25 10:04

MOT test number 336837631204

Advice Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 9/17



MOT #6 2011-08-25 10:04 MOT test number 535057431232

Result × Failed

Advice Rear Brake pipe slightly corroded (3.6.B.2c)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

MOT #5 2010-08-16 15:00

MOT test number 204438420285

Result ✓ Passed

MOT #4 2009-08-07 09:32

MOT test number 531079619274

Result \rightarrow Passed

MOT #3 2008-08-29 10:00

MOT test number 182212548201

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2007-09-11 10:33

MOT test number 221904057291

Result
✓ Passed

MOT #1 2006-09-19 09:33

MOT test number 252502766276

Result
✓ Passed

CarCheck.co.uk page 10/17



Tax & MOT check

Tax expired: 14 January 2021



Expired: 15 January 2021

X **MOT**

Tax status	Expired at 14 January 2021
Days left	1201 days too late
MOT expiry date	15 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 11/17



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
manners and the same of the sa	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 14/17



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 15/17



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-09-30
Last registration	2019-07-16
Complete history	See info



Registration #1	2003-09-30	18 mi
Registration #2	2006-09-19	12.405 mi
Registration #3	2007-09-11	18.127 mi
Registration #4	2008-08-29	22.904 mi
Registration #5	2009-08-07	27.640 mi
Registration #6	2010-08-16	31.562 mi
Registration #7	2011-08-25	34.117 mi
Registration #8	2012-05-31	36.003 mi
Registration #9	2012-06-01	36.003 mi
Registration #10	2013-05-25	42.143 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 16/17



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1467 mm
Length	3917 mm
Wheel base	2486 mm
Kerb weight	1075 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	3T24969 page 17/17