



R73VWL

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SHARAN CARAT
Colour	Blue
Year of manufacture	1997
Top speed	122 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	240 Nm at 4.200 rpm
Engine capacity	2.792 cc
Cylinders	6
Fuel type	Petrol




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-02
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-29
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	32
Total items failed	23

MOT #21	2023-09-30 06:35
---------	------------------

MOT test number	877594536677
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-29
------------------	------------

- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Underbody Corroded

**MOT #20**

2023-09-22 11:21

MOT test number

192171165494

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Underbody Corroded

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19

2018-02-21 09:27

MOT test number

279450527591

Result**✓ Passed****MOT #18**

2017-02-24 15:50

MOT test number

305039447377

Result**✓ Passed****MOT #17**

2017-02-22 09:34

MOT test number

462799229967

Result**✗ Failed**

Fail Offside Headlamp aim too low (1.8)

Fail Offside Front Braking system leaking caliper leaking fluid from bleed point (3.6.A.1)

Fail Nearside Headlamp excessively deteriorated so that the light output is severely reduced head lamp lens damaged and insecure (1.7.5a)

**MOT #16** 2016-02-22 08:47**MOT test number** 112507587923**Result** ✓ Passed**Advice** Slight discoloration to both front indicators**Advice** Rear brake pads showing wear**MOT #15** 2016-02-22 08:47**MOT test number** 397732599495**Result** ✗ Failed**Advice** Rear brake pads showing wear**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Slight discoloration to both front indicators**MOT #14** 2015-02-25 13:29**MOT test number** 387386455098**Result** ✓ Passed**Notice** Signs of slight lift to both front top suspension mountings**Notice** Both front tyres showing wear**Notice** Signs of central locking fault nearside rear door lock

**MOT #13**

2015-02-25 09:03

MOT test number

495336355010

Result

✗ Failed

- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
- Notice** Both front tyres showing wear
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Notice** Signs of slight lift to both front top suspension mountings

MOT #12

2013-08-24 09:55

MOT test number

599396133279

Result

✓ Passed

- Advice** Nearside Front Headlamp damaged but light output not reduced (1.7.5a)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Front Shock absorber has a slightly worn bush (2.7.4)

MOT #11

2012-08-22 16:37

MOT test number

465355632254

Result

✓ Passed

- Notice** Slight damage to nearside h/lamp glass

**MOT #10**

2012-08-22 12:46

MOT test number

488575932296

Result**✗ Failed****Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Track rod end loose (2.2.B.1d)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Slight damage to nearside h/lamp glass**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**MOT #9**

2011-08-22 10:12

MOT test number

185374231284

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8**

2011-08-22 09:04

MOT test number

437034231289

Result**✗ Failed****Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2010-07-28 16:11

MOT test number

810339400239

Result**✓ Passed**

**MOT #6** 2009-08-15 11:42**MOT test number** 894887729215**Result** ✓ Passed**MOT #5** 2008-08-21 10:53**MOT test number** 232504238238**Result** ✓ Passed**Notice** Slight damage and small hole to nearside head lamp glass**MOT #4** 2008-08-20 11:38**MOT test number** 521253638265**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Headlamp aim too far to the right (1.8)**Notice** Slight damage and small hole to nearside head lamp glass**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Headlamp aim too high and too far to the right. (1.8)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2007-08-24 10:01**MOT test number** 601476437222**Result** ✓ Passed**MOT #2** 2007-08-24 10:01**MOT test number** 771586737221**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #1	2006-08-22 11:17
MOT test number	901374436207
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
29 September 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		29 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 R73VWL
Plate since	2019-06-29
Current registration	 R73VWL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1997-11-04
Last registration	2023-09-30
Complete history	See info



Registration #1	1997-11-04	18 mi
Registration #2	2006-08-22	53.333 mi
Registration #3	2007-08-24	55.236 mi
Registration #4	2008-08-20	57.870 mi
Registration #5	2008-08-21	57.870 mi
Registration #6	2009-08-15	61.210 mi
Registration #7	2010-07-28	63.890 mi
Registration #8	2011-08-22	66.936 mi
Registration #9	2011-08-22	66.936 mi
Registration #10	2012-08-22	69.478 mi
Registration #11	2012-08-22	69.478 mi
Registration #12	2013-08-22	72.020 mi
Registration #13	2013-08-22	72.020 mi
Registration #14	2013-08-22	72.020 mi
Registration #15	2013-08-22	72.020 mi
Registration #16	2013-08-22	72.020 mi
Registration #17	2013-08-22	72.020 mi
Registration #18	2013-08-22	72.020 mi
Registration #19	2013-08-22	72.020 mi
Registration #20	2013-08-22	72.020 mi
Registration #21	2013-08-22	72.020 mi
Registration #22	2013-08-22	72.020 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of axles	2
Engine number	AAA241129