



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.600 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-10-21
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-03
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	42
Total items failed	3

MOT #15 2023-10-04 08:35

MOT test number 867122750978

Result ✓ Passed

Next expiry date 2024-10-03

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Central Front Tyre worn close to legal limit/worn on edge worn on inner edge 2054017 (5.2.3 (e))

Advice Exhaust has a minor leak of exhaust gases front flexi minor leak (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge 2054017 (5.2.3 (e))

MOT #14 2022-05-12 10:50

MOT test number 375360588227

Result ✓ Passed

Advice Rear Tyre worn close to legal limit/worn on edge both rears worn on inner edge (5.2.3 (e))

Advice Tyre different front to back

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened slightly corroded (1.1.14 (a) (ii))

Advice Exhaust has a minor leak of exhaust gases front flexi (6.1.2 (a))

**MOT #13** 2021-04-17 08:33**MOT test number** 124150536155**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2020-04-29 11:01**MOT test number** 569913498396**Result** ✓ Passed

- Minor** Nearside Windscreen wiper blade defective SPLIT ON ENDS (3.4 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened CORRODED ON INNER FACE (1.1.14 (a) (ii))
- Minor** Offside Windscreen wiper blade defective SPLIT ON ENDS (3.4 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened CORRODED ON INNER FACE (1.1.14 (a) (ii))

MOT #11 2020-04-29 11:01**MOT test number** 565378971447**Result** ✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened CORRODED ON INNER FACE (1.1.14 (a) (ii))
- Pass with rectification** Rear Exhaust silencer insecure 2 OUT OF 3 BROKEN OFF (8.1.1 (b) (i))
- Minor** Offside Windscreen wiper blade defective SPLIT ON ENDS (3.4 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened CORRODED ON INNER FACE (1.1.14 (a) (ii))
- Minor** Nearside Windscreen wiper blade defective SPLIT ON ENDS (3.4 (b) (i))

**MOT #10** 2019-03-25 10:06**MOT test number** 215030891892**Result** ✓ Passed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside non obligatory mirror damaged
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Coolant level low

MOT #9 2019-03-18 15:33**MOT test number** 884578434760**Result** ✗ Failed

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Tyre has ply or cords exposed inner edge worn (5.2.3 (d) (ii))
- Advice** Nearside non obligatory mirror damaged
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Fail** Nearside Front Tyre has ply or cords exposed outer side wall damaged (5.2.3 (d) (ii))
- Advice** Coolant level low
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #8 2018-04-03 08:00**MOT test number** 666328328291**Result** ✓ Passed

- Advice** Front tyres worn on inner edges

**MOT #7** 2017-02-18 09:32**MOT test number** 483627735146**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2016-02-20 11:34**MOT test number** 229108315078**Result** ✓ Passed

- Advice** Internal head lamp adjuster used prior to test.

MOT #5 2015-02-13 09:03**MOT test number** 707714645072**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #4 2014-02-21 10:19**MOT test number** 906312854084**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)



MOT #3 2013-02-16 10:15

MOT test number 117877843015

Result ✓ Passed

Notice Front brake discs lipped

Notice Front and rear brake pads getting low

MOT #2 2012-02-16 09:27

MOT test number 776357542053

Result ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1 2011-02-22 11:44

MOT test number 875323951027

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
3 October 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	3 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 HY08HGP
Plate since	2024-03-28
Current registration	 HY08HGP
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-11
Last registration	2023-10-04
Complete history	See info



Registration #1	2008-03-11	19 mi
Registration #2	2011-02-22	17.846 mi
Registration #3	2012-02-16	23.934 mi
Registration #4	2013-02-16	30.433 mi
Registration #5	2014-02-21	36.703 mi
Registration #6	2015-02-13	43.146 mi
Registration #7	2016-02-20	49.230 mi
Registration #8	2017-02-18	54.304 mi
Registration #9	2018-02-20	59.378 mi
Registration #10	2019-02-20	64.452 mi
Registration #11	2020-02-20	69.526 mi
Registration #12	2021-02-20	74.600 mi
Registration #13	2022-02-20	79.674 mi
Registration #14	2023-02-20	84.748 mi
Registration #15	2024-02-20	89.822 mi
Registration #16	2025-02-20	94.896 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1215 kg
Max. allowed weight	1505 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	20JS8835