





report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I
Colour	Blue
Year of manufacture	2007
Top speed	122 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	167 Nm at 4.500 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-17

Pictures 37

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



DA07TSV report date: 2024-03-28

MOT history

MOT expiry date	2025-04-17
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	29
Total items failed	3

MOT #21		2024-04-18 16:30
MOT test	number	349406200570
Result		✓ Passed
Next expiry date 2025-04-		2025-04-17
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #20		2024-04-18 08:13
MOT test nu	mber	813729414872
Result		X Failed
DANGEROUS Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice F	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #19	2023-06-23 09:16
MOT test number	202229659717
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #18 2022-06-24 11:00

MOT test number 367780933671

Result \rightarrow Passed

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing cracking outer tyre wall (5.2.3 (d) (ii))

MOT #17 2022-06-24 09:54

MOT test number 774287508103

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking outer tyre wall (5.2.3 (d) (ii))

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #16 2021-06-24 14:26

MOT test number 535238218041

Result ✓ Passed

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #15 2021-02-26 11:16

MOT test number 691588956555

Result

Passed

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #14 2020-02-25 11:44

MOT test number 847840043280

Result ✓ Passed

MOT #13 2019-03-04 10:45

MOT test number 901047561454

Result ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice

Under trays and engine covers fitted obscuring some components

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #11 2018-04-13 11:57 **MOT** test number 375783751251 Result **X** Failed **Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Front Brake pad(s) wearing thin (3.5.1g) Advice Under trays and engine covers fitted obscuring some components **Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Pass with rectification Offside Headlamp aim too high (1.8)

MOT #10		2017-04-10 15:23
MOT test	number	286453795571
Result		✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5)	5.1i)
Advice	Offside Rear coil spring corroded (2.4.C.1b)	

CarCheck.co.uk page 5/13



report date: 2024-03-28



MOT #8		2016-04-11 13:46
MOT test	number	730131596683
Result		× Failed
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Engine management light on dash	
Fail O	ffside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	

MOT #7	2015-03-26 17:15
MOT test number	436815485033
Result	✓ Passed
MOT #6	2015-03-25 11:19
MOT test number	809944885025
Result	X Failed
Fail Offside Front coil spring broken (2.4.C.1a)	

MOT #5	2014-06-18 14:27
MOT test number	267069664136
Result	✓ Passed
Notice Front tyres 3mm	

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #4 2013-06-14 10:33

MOT test number 536875463153

Result ✓ Passed

Advice Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #3 2012-06-25 10:39

MOT test number 145417072173

Result
✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Rear tyres starting to corrode.

MOT #2 2011-07-06 17:21

MOT test number 376537181195

Result ✓ Passed

MOT #1 2010-07-07 11:42

MOT test number 783738880125

Result ✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

Tax & MOT check





Tax status	Expired at 20 April 2024
Days left	10 days too late
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/13



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



DA07TSV report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-07-09
Last registration	2024-04-18
Complete history	See info



Registration #1	2007-07-09	18 mi
Registration #2	2010-07-07	17.441 mi
Registration #3	2011-07-06	22.339 mi
Registration #4	2012-06-25	27.307 mi
Registration #5	2013-06-14	32.651 mi
Registration #6	2014-06-18	38.424 mi
Registration #7	2015-03-25	43.390 mi
Registration #8	2015-03-26	43.394 mi
Registration #9	2016-04-11	52.333 mi
Registration #10	2016-04-11	52.333 mi
Registration #11	2017-04-10	58.847 mi
Registration #12	2018-04-13	63.496 mi
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		71.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 66
Registration #23		70,777 au

More info >

CarCheck.co.uk page 12/13



DA07TSV report date: 2024-03-28

Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1065 kg
Max. allowed weight	1365 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	L8 20203447

CarCheck.co.uk page 13/13