





report date: 2024-03-28

### General information

| Make                | PEUGEOT        |
|---------------------|----------------|
| Model               | 107 ACCESS     |
| Colour              | Blue           |
| Year of manufacture | 2012           |
| Top speed           | 99 mph         |
| 0 - 60 mph          | 14.2 seconds   |
| Gearbox             | 5 speed Manual |

### Engine & fuel consumption

| Power                   | 68 BHP             |
|-------------------------|--------------------|
| Max. torque             | 93 Nm at 3.600 rpm |
| Engine capacity         | 998 сс             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 55.4 mpg           |
| Consumption extra urban | 74.3 mpg           |
| Consumption combined    | 65.7 mpg           |
| CO2 emission            | 99 g/km            |
| CO2 label               | A                  |



CarCheck.co.uk page 1/12



# Internet history

### Entry 1

Date 2021-05-23

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date    | 2024-09-04 |
|--------------------|------------|
| MOT pass rate      | 83 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 2          |
| Total advice items | 9          |
| Total items failed | 1          |

| MOT #12  | 2023-08-25 14:25 |
|--|------------------|
| MOT test number  | 382330986334     |
| Result   | ✓ Passed         |
| Next expiry date   | 2024-09-04       |
| Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) |                  |

| MOT #11  | 2022-09-05 14:31 |
|--|------------------|
| MOT test number  | 436976379956     |
| Result   | ✓ Passed         |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #10  |  | 2021-11-12 15:06 |
|----------|--|------------------|
| MOT test | number   | 288297240033     |
| Result   |  | <b>✓</b> Passed  |
| Advice   | Offside Rear tyre cracking.                        |                  |
| Advice   | Exhaust system has corrosion.                      |                  |
| Advice   | Surface corrosion to front subframe and back axle. |                  |

| MOT #9          | 2020-11-05 15:53 |
|-----------------|------------------|
| MOT test number | 540297316151     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/12



**Advice** 

WF12ZYV

report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

 MOT #7
 2019-11-06 11:53

 MOT test number
 928397364216

 Result
 ✓ Passed

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2018-11-08 12:09

MOT test number 111641399942

Result ✓ Passed

MOT #5 2018-11-08 12:09
MOT test number 773359690344

**Result** X Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #4 2017-11-07 11:39
MOT test number 259096821626

MOT #3 2016-11-09 11:13
MOT test number 543356281364

CarCheck.co.uk page 4/12



MOT #2 2015-11-11 12:06

**MOT test number** 999833311666

**MOT #1** 2014-11-14 10:25

**MOT test number** 377968914309

**Notice** Rear tyres perishing between treads

CarCheck.co.uk page 5/12



### Tax & MOT check



| Tax status       | Valid until 1 June |
|------------------|--------------------|
| Days left        | 33                 |
| MOT expiry date  | 4 September 2024   |
| Full MOT history | See MOT history    |

### Tax calculation

| Vehicle class                           | 48             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



WF12ZYV

report date: 2024-03-28

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



WF12ZYV

report date: 2024-03-28

| Owner | hictory |
|-------|---------|
| Owner | HISLOLV |

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is |           | EOT |
|---|-----------|-----|
| *********   |           |     |
|   |           |     |
| ***************************************   |           |     |
| *********   |           |     |
|   |           |     |
| ***************************************   |           |     |
|   | More info | >   |
| Plate changes   |           |     |
| See in this check if this PEUGEOT had different number plates.  |           |     |
| Number of plates  |           |     |
| Current registration  | NK SIE    |     |
| Plate since   |           |     |
| Current registration  | UK UK     |     |
| Plate since   |           |     |
|   | More info | >   |
|   |           |     |

CarCheck.co.uk page 9/12



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 14         |
| First mileage registration | 2012-06-18 |
| Last registration          | 2023-08-25 |
| Complete history           | See info   |



| Registration #1  | 2012-06-18 | 15 mi     |
|------------------|------------|-----------|
| Registration #2  | 2014-11-14 | 19.822 mi |
| Registration #3  | 2015-11-11 | 23.187 mi |
| Registration #4  | 2016-11-09 | 26.501 mi |
| Registration #5  | 2017-11-07 | 29.604 mi |
| Registration #6  | 2018-11-08 | 32.640 mi |
| Registration #7  | 2018-11-08 | 32.640 mi |
| Registration #8  |            | 71.777 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 71.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.777 es |
|                  |            |           |

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

## Safety ratings

### Dimensions & weight

| Width               | 1630 mm |
|---------------------|---------|
| Height              | 1465 mm |
| Length              | 3430 mm |
| Wheel base          | 2340 mm |
| Kerb weight         | 900 kg  |
| Max. allowed weight | 1180 kg |

### Additional information

| Fuel tank capacity | 35 I                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |
| Number of seats    | 4                     |
| Number of axles    | 2                     |
| Engine number      | 7155098               |

CarCheck.co.uk page 12/12