



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D3 ES
Colour	Black
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	67.3 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





## MOT history

MOT expiry date	2021-06-11
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #10 2020-06-02 15:04

MOT test number 651004453808

Result ✓ Passed

Next expiry date 2021-06-11

**Advice** Under-trays fitted obscuring some underside components

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge approx 3mm @ 215/50 r17 W (5.2.3 (e))

MOT #9 2020-06-02 15:04

MOT test number 619442496713

Result ✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge approx 3mm @ 215/50 r17 W (5.2.3 (e))

**Advice** Under-trays fitted obscuring some underside components

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

MOT #8 2019-05-30 11:11

MOT test number 872677618899

Result ✓ Passed

MOT #7 2018-06-12 17:04

MOT test number 735573661405

Result ✓ Passed

**MOT #6** 2018-06-12 11:24**MOT test number** 693879896920**Result** ✗ Failed**MAJOR** Front Registration plate inscription illegible (0.1 (b))**MAJOR** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #5** 2017-03-29 14:26**MOT test number** 577753773667**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-03-31 16:30**MOT test number** 612962939908**Result** ✓ Passed**MOT #3** 2015-07-24 09:14**MOT test number** 825735105280**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2014-07-01 12:40**MOT test number** 549462984131**Result** ✓ Passed



MOT #1	2013-07-29 10:54
MOT test number	966920913254
Result	✓ Passed
<div>Notice Offside front tyre worn both edges</div>	



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>KY60DZA</b>
Plate since	2019-03-29
Current registration	<b>KY60DZA</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-09-10
Last registration	2020-06-02
Complete history	<a href="#">See info</a>



Registration #1	2010-09-10	9 mi
Registration #2	2013-07-29	53.605 mi
Registration #3	2014-07-01	64.794 mi
Registration #4	2015-07-24	76.737 mi
Registration #5	2016-03-31	81.189 mi
Registration #6	2017-03-29	92.547 mi
Registration #7	2018-03-29	95.277 mi
Registration #8	2019-03-29	95.277 mi
Registration #9	2020-03-29	95.277 mi
Registration #10	2021-03-29	95.277 mi
Registration #11	2022-03-29	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2775 mm
Kerb weight	1571 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	884841