



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 S D V50
Colour	Black
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-02
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-02
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	4

MOT #16	2023-09-01 09:10
MOT test number	997011061363
Result	✓ Passed
Next expiry date	2024-09-02

MOT #15	2023-08-16 10:54
MOT test number	243721690406
Result	✗ Failed
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Offside Front Service brake excessively binding (1.2.1 (f))
DANGEROUS	Offside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-09-02 07:18
MOT test number	598370431936
Result	✓ Passed

**MOT #13** 2022-09-01 12:50**MOT test number** 698171161077**Result** ✗ Failed**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/50x17 (5.2.3 (d) (i))**MOT #12** 2021-09-03 13:44**MOT test number** 767183088402**Result** ✓ Passed**MOT #11** 2020-08-22 11:00**MOT test number** 206384206977**Result** ✓ Passed**MOT #10** 2019-09-23 13:13**MOT test number** 448023867497**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2018-09-25 16:53**MOT test number** 699212585092**Result** ✓ Passed

**MOT #8** 2017-10-13 13:36**MOT test number** 618221934486**Result** ✓ Passed**MOT #7** 2016-11-15 16:44**MOT test number** 916835549154**Result** ✓ Passed**Advice** Covers fitted to engine and under car**MOT #6** 2015-11-12 08:59**MOT test number** 567353941986**Result** ✓ Passed**Advice** Covers fitted to engine and under car**MOT #5** 2015-11-11 13:18**MOT test number** 563801255315**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Covers fitted to engine and under car**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2014-12-04 15:43**MOT test number** 425478534376**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #3	2013-11-28 11:16
MOT test number	965802833303
Result	✓ Passed
MOT #2	2012-12-21 09:32
MOT test number	567206752336
Result	✓ Passed
MOT #1	2012-12-13 09:55
MOT test number	438688942352
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	2 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AD59HVV
Plate since	2019-03-28
Current registration	AD59HVV
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-16
Last registration	2023-09-01
Complete history	See info



Registration #1	2009-12-16	22 mi
Registration #2	2012-12-13	23.747 mi
Registration #3	2012-12-21	23.768 mi
Registration #4	2013-11-28	30.375 mi
Registration #5	2014-12-04	37.205 mi
Registration #6	2015-11-11	43.007 mi
Registration #7	2015-11-12	43.007 mi
Registration #8	2016-11-15	48.104 mi
Registration #9	2017-10-13	56.244 mi
Registration #10	2018-05-22	65.377 mi
Registration #11	2018-05-22	65.377 mi
Registration #12	2018-05-22	65.377 mi
Registration #13	2018-05-22	65.377 mi
Registration #14	2018-05-22	65.377 mi
Registration #15	2018-05-22	65.377 mi
Registration #16	2018-05-22	65.377 mi
Registration #17	2018-05-22	65.377 mi
Registration #18	2018-05-22	65.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1519 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

565929