



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SL SL 350
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	6.6 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	272 BHP
Max. torque	350 Nm at 2.400 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.4 mpg
CO2 emission	246 g/km
CO2 label	L





Internet history

Entry 4

Date	2022-12-16
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 3

Date	2021-12-24
Pictures	32
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-11-02
Pictures	32
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-09-17
------	------------

Pictures

32

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-10-13
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #16	2023-10-14 11:27
MOT test number	659210917110
Result	✓ Passed
Next expiry date	2024-10-13
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2022-11-19 11:51
MOT test number	246310038476
Result	✓ Passed
Advice	Front Wheel bearing has slight play Both front. (5.1.3 (a) (i))
Advice	Front Tyre slightly damaged/cracking or perishing Both front. (5.2.3 (d) (ii))

MOT #14	2021-11-02 17:19
MOT test number	293953757518
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))

**MOT #13** 2021-10-23 11:41**MOT test number** 297563409584**Result** ✗ Failed **DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**Advice** Front Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))**MOT #12** 2021-01-12 15:02**MOT test number** 350680029645**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-01-06 12:57**MOT test number** 758245226362**Result** ✓ Passed**MOT #10** 2018-11-15 11:38**MOT test number** 624286852870**Result** ✓ Passed**MOT #9** 2017-10-05 07:34**MOT test number** 188706254360**Result** ✓ Passed**MOT #8** 2016-09-12 08:34**MOT test number** 397281677642**Result** ✓ Passed

**MOT #7** 2015-09-02 09:19**MOT test number** 357010218131**Result** ✓ Passed

- Advice** Secondary brake lamp not working
- Advice** Offside Rear worn close to legal limit
- Advice** Offside rear wheel has slight buckle
- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear tyre close to legal limit

MOT #6 2015-06-29 13:54**MOT test number** 398100985157**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Windscreen has small chip in zone A
- Notice** OSF WHEEL SLIGHT BUCKLE
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** THRID BRAKE LAMP NOT WORKING
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #5 2014-07-24 12:37**MOT test number** 498905704237**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4** 2013-07-17 16:07**MOT test number** 947758693116**Result** ✓ Passed**Notice** Low pitch horn n/w**Advice** Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Both rear tyres just above legal limit**MOT #3** 2012-08-06 14:19**MOT test number** 378529112413**Result** ✓ Passed**MOT #2** 2011-05-31 14:10**MOT test number** 465831651128**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2010-05-25 11:34**MOT test number** 582615340156**Result** ✓ Passed**Notice** CHIP IN WINDSCREEN OFFSIDE IN SWEPT AREA WITHIN 10MM



Tax & MOT check

X

Untaxed

Tax expired:
3 June 2021

✓

MOT

Expires:
13 October 2024

Tax status	Expired at 3 June 2021
Days left	1061 days too late
MOT expiry date	13 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	EA07OWW
Plate since	2019-06-29
Current registration	EA07OWW
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-05-24
Last registration	2023-10-14
Complete history	See info



Registration #1	2007-05-24	16 mi
Registration #2	2010-05-25	28.760 mi
Registration #3	2011-05-31	38.208 mi
Registration #4	2012-08-06	51.365 mi
Registration #5	2013-07-17	60.791 mi
Registration #6	2014-07-24	72.028 mi
Registration #7	2015-06-29	83.823 mi
Registration #8	2015-09-02	83.825 mi
Registration #9	2016-09-12	89.995 mi
Registration #10	2017-10-05	95.892 mi
Registration #11	2018-11-15	99.443 mi
Registration #12	2019-05-20	99.999 mi
Registration #13	2019-05-20	99.999 mi
Registration #14	2019-05-20	99.999 mi
Registration #15	2019-05-20	99.999 mi
Registration #16	2019-05-20	99.999 mi
Registration #17	2019-05-20	99.999 mi
Registration #18	2019-05-20	99.999 mi
Registration #19	2019-05-20	99.999 mi
Registration #20	2019-05-20	99.999 mi
Registration #21	2019-05-20	99.999 mi

More info >



Dimensions & weight

Width	2033 mm
Height	1317 mm
Length	4532 mm
Wheel base	2560 mm
Kerb weight	1825 kg

Additional information

Fuel tank capacity	88 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27296630585474