



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Grey
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-06
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-04
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	21
Total items failed	13

MOT #21 2024-01-05 08:48

MOT test number 742828131965

Result ✓ Passed

Next expiry date 2025-01-04

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Play in steering rack inner joint(s)

MOT #20 2023-01-04 08:57

MOT test number 232798557945

Result ✓ Passed

Advice Rear Tyre worn close to legal limit/worn on edge both sides 2.5mm (5.2.3 (e))

MOT #19 2023-01-04 08:57

MOT test number 215409718126

Result ✗ Failed

Advice Rear Tyre worn close to legal limit/worn on edge both sides 2.5mm (5.2.3 (e))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #18**

2022-01-04 11:54

MOT test number

393028556186

Result

✓ Passed

Advice

Offside Play in steering rack inner joint(s)

Advice

Vehicles internal headlight adjuster altered to recheck lights

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2022-01-04 09:39

MOT test number

907641151808

Result

✗ Failed

Fail

Exhaust emissions exceed manufacturer's specified limit 1.8 limit (8.2.2.2 (a))

Advice

Offside Play in steering rack inner joint(s)

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Vehicles internal headlight adjuster altered to recheck lights

Fail

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #16

2020-12-12 10:35

MOT test number

561042530569

Result

✓ Passed

MOT #15

2020-12-12 09:37

MOT test number

243038408077

Result

✗ Failed

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14** 2019-06-13 11:27**MOT test number** 386660927784**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2018-07-05 15:26**MOT test number** 413931940530**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-06-08 11:55**MOT test number** 891468046343**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine Reading = 4.44 & Spec = 2.5 (8.2.2.2 (b))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge VERY ! BALD ! On inner edge and 3mm over 3/4 of the tread. DANGEROUS ! (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm on outer edge and 4mm over 3/4 of the tread (5.2.3 (e))**Fail** Front Windscreen washer not working (3.5 (a))**MOT #11** 2017-03-28 15:12**MOT test number** 547931366640**Result** ✓ Passed**Advice** Screw in nearside rear tyre

**MOT #10** 2017-03-28 15:12**MOT test number** 507234728608**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Screw in nearside rear tyre**MOT #9** 2016-02-10 11:43**MOT test number** 854948885900**Result** ✓ Passed**MOT #8** 2016-02-10 11:43**MOT test number** 282267956531**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #7** 2015-02-25 15:13**MOT test number** 186096855462**Result** ✓ Passed**MOT #6** 2014-03-24 09:41**MOT test number** 677103984030**Result** ✓ Passed**Notice** Both front tyres wearing on edges

**MOT #5** 2014-03-24 09:41**MOT test number** 119183384426**Result** ✗ Failed**Notice** Both front tyres wearing on edges**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2013-03-14 08:42**MOT test number** 436953273057**Result** ✓ Passed**MOT #3** 2012-03-22 09:45**MOT test number** 145162682407**Result** ✓ Passed**Notice** Both rear tyres perishing**MOT #2** 2011-03-30 09:43**MOT test number** 146049581491**Result** ✓ Passed**MOT #1** 2010-04-01 11:20**MOT test number** 622351590083**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-31
Last registration	2024-01-05
Complete history	See info



Registration #1	2007-03-31	11 mi
Registration #2	2010-04-01	17.183 mi
Registration #3	2011-03-30	21.285 mi
Registration #4	2012-03-22	26.059 mi
Registration #5	2013-03-14	32.420 mi
Registration #6	2014-03-24	38.233 mi
Registration #7	2015-02-25	42.242 mi
Registration #8	2016-02-10	47.427 mi
Registration #9	2016-02-10	47.427 mi
Registration #10	2017-03-28	55.105 mi
Registration #11	2017-03-28	55.105 mi
Registration #12	2018-03-28	62.217 mi
Registration #13	2018-03-28	62.217 mi
Registration #14	2018-03-28	62.217 mi
Registration #15	2018-03-28	62.217 mi
Registration #16	2018-03-28	62.217 mi
Registration #17	2018-03-28	62.217 mi
Registration #18	2018-03-28	62.217 mi
Registration #19	2018-03-28	62.217 mi
Registration #20	2018-03-28	62.217 mi
Registration #21	2018-03-28	62.217 mi
Registration #22	2018-03-28	62.217 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB660199901