



General information

Make	VOLKSWAGEN
Model	TOURAN R LINE TDI 4MOTION
Colour	Black
Year of manufacture	2010
Top speed	125 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-10-22
Pictures	33
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-08-22
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	31
Total items failed	5

MOT #15 2023-08-18 15:10**MOT test number** 518106806254**Result** Passed**Next expiry date** 2024-08-22**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2023-08-18 14:11**MOT test number** 904839249181**Result** Failed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #13**

2022-08-19 15:40

MOT test number

633964421707

Result

✓ Passed

Minor Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12**

2021-08-18 10:01

MOT test number

314765799627

Result

✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11**

2021-08-18 10:01

MOT test number

944136423714

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #10** 2020-08-20 11:12**MOT test number** 934119186365**Result** ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9 2019-08-20 13:42**MOT test number** 303058885941**Result** ✓ Passed**MOT #8** 2019-08-20 13:42**MOT test number** 974011798754**Result** ✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7 2018-08-23 12:50**MOT test number** 203118827888**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Fuel filter weeping

MOT #6 2018-08-23 12:50**MOT test number** 721955584734**Result** ✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Advice Fuel filter weeping

Pass with rectification Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #5** 2017-08-04 14:01**MOT test number** 576297447629**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2016-06-29 13:07**MOT test number** 966082807644**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2015-04-02 11:49**MOT test number** 569722595019**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-03-24 15:00**MOT test number** 996233384030**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-03-05 11:08**MOT test number** 685724763068**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 August 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	LR10YYL
Plate since	2024-03-29
Current registration	LR10YYL
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-30
Last registration	2023-08-18
Complete history	See info



Registration #1	2010-03-30	29 mi
Registration #2	2013-03-05	29.074 mi
Registration #3	2014-03-24	39.806 mi
Registration #4	2015-04-02	49.995 mi
Registration #5	2016-06-29	64.971 mi
Registration #6	2017-08-04	77.536 mi
Registration #7	2018-08-23	87.011 mi
Registration #8	2018-08-23	87.011 mi
Registration #9	2019-08-20	93.672 mi
Registration #10	2020-08-18	100.000 mi
Registration #11	2021-08-18	100.000 mi
Registration #12	2022-08-18	100.000 mi
Registration #13	2023-08-18	100.000 mi
Registration #14	2024-03-29	100.000 mi
Registration #15	2024-03-29	100.000 mi
Registration #16	2024-03-29	100.000 mi
Registration #17	2024-03-29	100.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1609 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

CBB 328529