




report date: 2024-03-28

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Silver
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	M





MOT history

MOT expiry date	2022-01-05
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	18
Total items failed	11

MOT #18	2021-01-06 17:50
MOT test number	618904893479
Result	✓ Passed
Next expiry date	2022-01-05
Advice	Central Rear Prop shaft bearing has slight play (6.1.7 (b) (i))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2019-12-12 12:27
MOT test number	839572530136
Result	✓ Passed

MOT #16	2019-11-23 14:03
MOT test number	873067992755
Result	✗ Failed
MAJOR	Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #15** 2018-12-03 12:42**MOT test number** 514278254251**Result** ✓ Passed**MOT #14** 2017-12-07 15:50**MOT test number** 590644007438**Result** ✓ Passed**MOT #13** 2017-11-30 14:55**MOT test number** 932023081206**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Rear brake application uneven (3.7.B.2)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #12** 2016-12-09 10:56**MOT test number** 337953660154**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front bumper has slight damage**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #11** 2015-10-22 06:44**MOT test number** 220450109579**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #10** 2015-10-21 15:16**MOT test number** 969702808096**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #9** 2014-10-13 14:28**MOT test number** 398156884480**Result** ✓ Passed**Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2013-11-08 10:13**MOT test number** 776042113317**Result** ✓ Passed**MOT #7** 2012-10-22 16:31**MOT test number** 448876792274**Result** ✓ Passed**Notice** Steering rack mounting bushes worn**MOT #6** 2012-10-22 12:42**MOT test number** 168026192292**Result** ✗ Failed**Notice** Steering rack mounting bushes worn**Fail** Offside Front passenger door cannot be opened from outside the vehicle (6.2.B.1c)

**MOT #5** 2011-10-24 15:23**MOT test number** 837667491283**Result** ✓ Passed**MOT #4** 2011-10-20 12:00**MOT test number** 425773991223**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #3 2010-10-21 12:58**MOT test number** 360424190496**Result** ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2010-10-20 17:48**MOT test number** 811433990204**Result** ✗ Failed

- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1 2010-02-05 14:52**MOT test number** 542316630042**Result** ✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-01-01
Last registration	2021-01-06
Complete history	See info



Registration #1	2007-01-01	10 mi
Registration #2	2010-02-05	70.142 mi
Registration #3	2010-10-20	75.181 mi
Registration #4	2010-10-21	75.181 mi
Registration #5	2011-10-20	86.565 mi
Registration #6	2011-10-24	86.615 mi
Registration #7	2012-10-22	96.550 mi
Registration #8	2012-10-22	96.550 mi
Registration #9	2013-11-08	106.156 mi
Registration #10	2014-10-13	118.655 mi
Registration #11	2015-10-20	121.277 mi
Registration #12	2016-10-20	121.277 mi
Registration #13	2017-10-20	121.277 mi
Registration #14	2018-10-20	121.277 mi
Registration #15	2019-10-20	121.277 mi
Registration #16	2020-10-20	121.277 mi
Registration #17	2021-01-06	121.277 mi
Registration #18	2021-01-06	121.277 mi
Registration #19	2021-01-06	121.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1763 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2208 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	865510