



General information

Make	FORD
Model	FIESTA EDGE
Colour	Silver
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	109 Nm at 3.600 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-05-26
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-05-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	29
Total items failed	2

MOT #15	2022-05-06 12:37
MOT test number	188200180105
Result	✓ Passed
Next expiry date	2023-05-05
Advice	Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

MOT #14	2022-05-04 11:36
MOT test number	464790014010
Result	✗ Failed
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13**

2021-05-06 09:21

MOT test number

120639616406

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn and offside rear (5.1.2 (b) (i))
- Advice** Rear Exhaust heat shield loose
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2021-05-06 08:22

MOT test number

244372014089

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn and offside rear (5.1.2 (b) (i))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust heat shield loose
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11

2020-06-11 08:25

MOT test number

562470798390

Result

✓ Passed

MOT #10

2019-04-24 09:01

MOT test number

454827834834

Result

✓ Passed

**MOT #9** 2018-04-25 08:55**MOT test number** 282438483619**Result** ✓ Passed**MOT #8** 2018-03-22 15:21**MOT test number** 512976242109**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2017-03-23 12:34**MOT test number** 931867671251**Result** ✓ Passed**MOT #6** 2017-03-23 08:57**MOT test number** 185199111172**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit on edge 195/50/15 (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on tread (4.1.D.1a)**Advice** Nearside Front Tyre worn close to the legal limit on edge (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear tyre cracking on tread not at cords at time of test**MOT #5** 2016-03-25 15:53**MOT test number** 927162953419**Result** ✓ Passed

**MOT #4** 2015-09-23 11:12**MOT test number** 754673100678**Result** ✓ Passed**Advice** Osf and NSF tyres cracking on tread**MOT #3** 2014-09-23 11:39**MOT test number** 555006864229**Result** ✓ Passed**Notice** All 4 tyres have cracking in base of treads**MOT #2** 2013-08-21 13:23**MOT test number** 817653633217**Result** ✓ Passed**MOT #1** 2013-08-21 13:23**MOT test number** 205523433281**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✕
Untaxed

Tax expired:
27 January 2023

✕
MOT

Expired:
5 May 2023

Tax status	Expired at 27 January 2023
Days left	459 days too late
MOT expiry date	5 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-29
Last registration	2022-05-06
Complete history	See info



Registration #1	2010-03-29	16 mi
Registration #2	2013-08-21	12.773 mi
Registration #3	2014-09-23	14.392 mi
Registration #4	2015-09-23	15.481 mi
Registration #5	2016-03-25	16.235 mi
Registration #6	2017-03-23	23.086 mi
Registration #7	2017-03-23	23.086 mi
Registration #8	2018-03-22	27.860 mi
Registration #9	2019-05-20	35.277 mi
Registration #10	2019-05-20	35.277 mi
Registration #11	2019-05-20	35.277 mi
Registration #12	2019-05-20	35.277 mi
Registration #13	2019-05-20	35.277 mi
Registration #14	2019-05-20	35.277 mi
Registration #15	2019-05-20	35.277 mi
Registration #16	2019-05-20	35.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1098 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number

9K62960