



**AK09DGU**


report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Silver
Year of manufacture	2009
Top speed	125 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-08-12
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-11
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-30
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	15
Total items failed	6

MOT #15	2023-10-31 11:27
MOT test number	155011825044
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14	2023-10-31 11:27
MOT test number	973053305160
Result	✗ Failed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13** 2022-09-13 11:43**MOT test number** 620956869326**Result** ✓ Passed**Advice** Nearside Rear tyre on 3 mm / screw in**Advice** Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2021-09-30 08:30**MOT test number** 169338048417**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #11** 2020-10-02 14:55**MOT test number** 302799611325**Result** ✓ Passed**MOT #10** 2020-03-18 15:36**MOT test number** 311617038927**Result** ✓ Passed**MOT #9** 2020-03-16 14:37**MOT test number** 533752999064**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #8** 2019-08-28 09:55**MOT test number** 589284993573**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2018-08-29 13:33**MOT test number** 744351061746**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #6** 2017-08-18 17:45**MOT test number** 226097918192**Result** ✓ Passed**MOT #5** 2017-08-10 16:55**MOT test number** 929147217992**Result** ✗ Failed**Fail** Nearside Rear Rear wheel bearing rough when rotated (2.6.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2016-08-19 11:52**MOT test number** 644519168316**Result** ✓ Passed**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-09-01 07:17**MOT test number** 481147346112**Result** ✓ Passed



MOT #2	2015-08-29 11:04
MOT test number	383536945361
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)
Advice	Rear Tyre worn close to the legal limit both also all perishing (4.1.E.1)

MOT #1	2012-01-24 14:27
MOT test number	386834022008
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
30 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	30 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>AK09DGU</b>
Plate since	2019-03-28
Current registration	<b>AK09DGU</b>
Plate since	2019-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-06
Last registration	2023-10-31
Complete history	<a href="#">See info</a>



Registration #1	2009-03-06	9 mi
Registration #2	2012-01-24	17.075 mi
Registration #3	2015-08-29	24.295 mi
Registration #4	2015-09-01	24.295 mi
Registration #5	2016-08-19	36.339 mi
Registration #6	2017-08-10	48.984 mi
Registration #7	2017-08-18	48.984 mi
Registration #8	2018-08-29	58.638 mi
Registration #9	2019-08-28	63.286 mi
Registration #10	2020-08-28	75.330 mi
Registration #11	2021-08-28	87.374 mi
Registration #12	2022-08-28	99.418 mi
Registration #13	2023-08-28	111.462 mi
Registration #14	2024-08-28	123.506 mi
Registration #15	2025-08-28	135.550 mi
Registration #16	2026-08-28	147.594 mi
Registration #17	2027-08-28	159.638 mi
Registration #18	2028-08-28	171.682 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	090622085755BG