



HONDA




report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA ES
Colour	Black
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	121 Nm at 4.500 rpm
Cylinders	4
Fuel type	Hybrid / Electric / (clean)
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg





Internet history

Entry 1

Date	2021-07-31
Pictures	6
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #13	2021-07-28 14:36
MOT test number	424279328467
Result	✓ Passed
Next expiry date	2022-07-27

MOT #12	2021-06-22 16:24
MOT test number	418995906162
Result	✗ Failed

Advice Rear Shock absorbers has slight external damage to the casing Both heavily corroded (5.3.2 (b))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Service brake binding but not excessively (1.2.1 (f))

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))

Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Rear Service brake excessively fluctuating (1.2.1 (e))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11	2020-07-20 14:42
MOT test number	530205544684
Result	✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2019-07-03 14:24
MOT test number	586360738635
Result	✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2018-05-01 14:30**MOT test number** 190458262605**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8** 2018-05-01 12:59**MOT test number** 526228855555**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2017-05-01 14:55**MOT test number** 887294140241**Result** ✓ Passed**MOT #6** 2016-05-09 14:49**MOT test number** 896472373313**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #5** 2015-05-15 15:41**MOT test number** 178905935111**Result** ✓ Passed**MOT #4** 2014-05-07 12:05**MOT test number** 888957324169**Result** ✓ Passed



MOT #3	2013-05-17 15:10
MOT test number	439377433128
Result	✓ Passed

MOT #2	2013-05-17 12:08
MOT test number	228967933467
Result	✗ Failed
<div><div>Advice</div>Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)</div> <div><div>Fail</div>Nearside Rear rear brake binding (3.7.B.1)</div> <div><div>Advice</div>Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)</div> <div><div>Fail</div>Offside Rear rear brake binding (3.7.B.1)</div>	

MOT #1	2012-05-21 12:31
MOT test number	379132642115
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	SD09XPZ
Plate since	2024-03-28
Current registration	SD09XPZ
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-05-22
Last registration	2021-07-28
Complete history	See info



Registration #1	2009-05-22	22 mi
Registration #2	2012-05-21	20.189 mi
Registration #3	2013-05-17	24.585 mi
Registration #4	2013-05-17	24.585 mi
Registration #5	2014-05-07	29.056 mi
Registration #6	2015-05-15	32.390 mi
Registration #7	2016-05-09	35.555 mi
Registration #8	2017-05-01	38.536 mi
Registration #9	2018-05-01	41.517 mi
Registration #10	2019-05-01	44.498 mi
Registration #11	2020-05-01	47.479 mi
Registration #12	2021-05-01	50.460 mi
Registration #13	2022-05-01	53.441 mi
Registration #14	2023-05-01	56.422 mi
Registration #15	2024-05-01	59.403 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 1028021