



report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO MULTIJET SPORT
Colour	Black
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	165 BHP
Max. torque	360 Nm at 1.750 rpm
Engine capacity	1.956 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-09-27
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-05
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	65
Total items failed	20

MOT #18	2023-11-06 14:08
---------	------------------

MOT test number	142359074283
-----------------	--------------

Result	✓ Passed
Next expiry date	2024-11-05
Advice	Outer sill covers fitted
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Exhaust outer skin missing
Minor	Nearside Front Tyre obviously under inflated (5.2.3 (I))
Advice	Front Front subframe surface corrosion
Advice	Nearside Rear Coil spring corroded
Advice	Rear Rear beam axle heavy surface corrosion
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Front Crossmember surface corrosion



MOT #17

2023-10-31 09:00

MOT test number

923352664448

Result

✗ Failed

- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Minor

Nearside Front Tyre obviously under inflated (5.2.3 (I))
- Advice

Front Front subframe surface corrosion
- Advice

Nearside Rear Coil spring corroded
- Fail

Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice

Rear Rear beam axle heavy surface corrosion
- Advice

Rear Exhaust mounting defective (6.1.2 (a))
- Advice

Rear Exhaust outer skin missing
- Advice

Front Crossmember surface corrosion
- Fail

Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))
- Advice

Outer sill covers fitted

**MOT #16**

2023-10-20 11:19

**MOT test number**

547491159898

**Result****✗ Failed**

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Front subframe corrosion
- Advice** Offside Rear Suspension component corroded but not seriously weakened suspension mount (5.3.3 (b) (i))
- Fail** Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Lower gearbox mount slightly perished
- Advice** Nearside Rear Suspension component corroded but not seriously weakened suspension mount (5.3.3 (b) (i))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear exhaust outer skin peeling
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2022-10-19 09:17

**MOT test number**

628341248383

**Result****✓ Passed**

- Advice** Nearside Front Headlight bolt missing light still secure
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear exhaust box corroded
- Advice** Coolant leak

**MOT #14**

2022-10-17 13:06

**MOT test number**

226549665027

**Result****✗ Failed****Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear exhaust box corroded**Advice** Coolant leak**Fail** Front Exhaust fumes causing a danger to health of persons on board Flexi broken (6.1.2 (b) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Headlight bolt missing light still secure**MOT #13**

2021-10-13 13:07

**MOT test number**

374845095788

**Result****✓ Passed****Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Rear exhaust box sightly deteriorated**MOT #12**

2020-09-29 14:19

**MOT test number**

139136283154

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

**MOT #11**

2020-09-28 11:14

**MOT test number**

605448068047

**Result****✗ Failed**

**Fail** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**Fail** Nearside Front Coil spring fractured or broken broken (5.3.1 (b) (i))

**Fail** Offside Front Inner Tyre has a lump, caused by separation or partial failure of its structure wall out of shape (5.2.3 (d) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

**Fail** Offside Front Lower Suspension arm pin or bush excessively worn arm rear bush worn (5.3.4 (a) (i))

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #10**

2019-09-30 11:55

**MOT test number**

959806797404

**Result****✓ Passed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2019-09-30 09:54

**MOT test number**

269497041958

**Result****✗ Failed**

**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2018-10-01 13:41

**MOT test number**

339066140776

**Result****✓ Passed**

**Advice** Exhaust mounting defective Backbox mounting split (6.1.2 (a))

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #7** 2018-09-29 08:06**MOT test number** 580858540494**Result** ✗ Failed

- Minor** Nearside Rear Brake hose slightly twisted (1.1.12 (b) (i))
- Fail** Nearside Rear Service brake imbalanced across an axle (1.2.1 (b) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Rear Brake pivot has restricted free movement Caliper lever (1.1.15 (e))
- Advice** Exhaust mounting defective Backbox mounting split (6.1.2 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #6** 2017-09-27 10:53**MOT test number** 883176733167**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear exhaust corroded
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2016-10-04 15:03**MOT test number** 935670167983**Result** ✓ Passed



**MOT #4** 2016-09-28 10:32**MOT test number** 437784456622**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner faces (3.5.1i)**MOT #3** 2015-09-10 14:54**MOT test number** 705650246939**Result** ✓ Passed**MOT #2** 2014-09-10 15:04**MOT test number** 877443854248**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-08-21 12:44**MOT test number** 305733833254**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
5 November 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	5 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-31
Last registration	2023-11-06
Complete history	<a href="#">See info</a>



Registration #1	2010-03-31	17 mi
Registration #2	2013-08-21	47.713 mi
Registration #3	2014-09-10	67.110 mi
Registration #4	2015-09-10	75.842 mi
Registration #5	2016-09-28	81.304 mi
Registration #6	2016-10-04	81.304 mi
Registration #7	2017-09-27	86.671 mi
Registration #8	2018-09-29	96.362 mi
Registration #9	2018-10-01	96.367 mi
Registration #10	2019-09-30	112.401 mi
Registration #11	2019-10-01	112.401 mi
Registration #12	2019-10-01	112.401 mi
Registration #13	2019-10-01	112.401 mi
Registration #14	2019-10-01	112.401 mi
Registration #15	2019-10-01	112.401 mi
Registration #16	2019-10-01	112.401 mi
Registration #17	2019-10-01	112.401 mi
Registration #18	2019-10-01	112.401 mi
Registration #19	2019-10-01	112.401 mi
Registration #20	2019-10-01	112.401 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1360 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5



Number of axles	2
Engine number	6468904