



CITROËN



report date: 2024-03-28

General information

| | |
|---------------------|---------------------|
| Make | CITROEN |
| Model | XSARA 16V EXCLUSIVE |
| Colour | Red |
| Year of manufacture | 2009 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 107 BHP |
| Max. torque | 147 Nm at 4.000 rpm |
| Engine capacity | 1.587 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.0 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 39.2 mpg |
| CO2 emission | 172 g/km |
| CO2 label | H |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-25 |
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 3 |

| | |
|------------------|--|
| MOT #13 | 2024-02-26 16:44 |
| MOT test number | 457074931743 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-25 |
| Minor | Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |

| | |
|-----------------|---|
| MOT #12 | 2024-02-21 15:37 |
| MOT test number | 505004239767 |
| Result | ✗ Failed |
| Fail | Nearside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i)) |
| Minor | Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Fail | Offside Outer Integral body structure has excessive corrosion which adversely affects braking or steering sill (6.1.1 (c) (ii)) |
| Fail | Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #11 | 2023-02-14 12:05 |
| MOT test number | 767230261473 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #10 | 2022-02-25 13:30 |
| MOT test number | 531742647061 |
| Result | ✓ Passed |



| | |
|---------------|------------------|
| MOT #9 | 2020-09-17 11:10 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 405950244416 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #8 | 2019-09-16 10:31 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 682192240460 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #7 | 2018-09-11 09:51 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 579075333037 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #6 | 2017-09-08 09:26 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 108784163512 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2016-09-08 08:43 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 659199000582 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2015-09-08 09:50 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 799879211744 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|---|
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
|---------------|---|

| | |
|---------------|------------------|
| MOT #3 | 2014-09-09 10:39 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 599602254273 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



| | |
|-----------------|------------------|
| MOT #2 | 2013-09-09 09:41 |
| MOT test number | 969392853237 |
| Result | ✓ Passed |
| MOT #1 | 2012-09-25 12:45 |
| MOT test number | 276119562225 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 25 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | BN59XTH |
| Plate since | 2019-09-29 |
| Current registration | BN59XTH |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2009-09-28 |
| Last registration | 2024-02-26 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-09-28 | 18 mi |
| Registration #2 | 2012-09-25 | 12.523 mi |
| Registration #3 | 2013-09-09 | 18.673 mi |
| Registration #4 | 2014-09-09 | 24.628 mi |
| Registration #5 | 2015-09-08 | 27.849 mi |
| Registration #6 | 2016-09-08 | 31.176 mi |
| Registration #7 | 2017-09-08 | 33.787 mi |
| Registration #8 | 2018-09-08 | 35.277 mi |
| Registration #9 | 2019-09-08 | 36.277 mi |
| Registration #10 | 2020-09-08 | 37.277 mi |
| Registration #11 | 2021-09-08 | 38.277 mi |
| Registration #12 | 2022-09-08 | 39.277 mi |
| Registration #13 | 2023-09-08 | 40.277 mi |
| Registration #14 | 2024-02-26 | 41.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 83% |
| Children | 74% |
| Pedestrian | 33% |
| Safety systems | 40% |
| Overall rating | 67% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1667 mm |
| Height | 1612 mm |
| Length | 3860 mm |
| Wheel base | 2460 mm |
| Kerb weight | 1133 kg |
| Max. allowed weight | 1597 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 47 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | FX7S3417498 |