



report date: 2024-03-29

General information

Make	CITROEN
Model	C1 PURETECH FLAIR
Colour	Grey
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	82 BHP
Max. torque	116 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2



Date	2021-07-26
Pictures	57
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-07-16
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-05
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #5	2023-07-28 14:16
MOT test number	875682459815
Result	✓ Passed
Next expiry date	2024-08-05
Advice	Offside Front Tyre slightly damaged/cracking or perishing 165/60/15 (5.2.3 (d) (ii))
Advice	Offside Rear Tyre heavily perished
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre heavily perished

**MOT #4** 2023-07-28 09:35**MOT test number** 714430407086**Result** ✗ Failed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing 165/60/15 (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre heavily perished
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** TPMS light on
- Advice** Nearside Rear Tyre heavily perished
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #3** 2022-07-25 12:04**MOT test number** 310483426854**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked on tread area (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked on tread area (5.2.3 (d) (ii))

**MOT #2** 2021-08-06 14:36**MOT test number** 946578250150**Result** ✓ Passed



MOT #1	2020-11-17 09:17
MOT test number	117303755994
Result	✓ Passed
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
5 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	5 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>First licence fee (12 months)</b>	£ 165,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-27
Last registration	2023-07-28
Complete history	<a href="#">See info</a>



Registration #1	2017-11-27	16 mi
Registration #2	2020-11-17	25.049 mi
Registration #3	2022-05-20	25.277 mi
Registration #4	2022-05-20	25.277 mi
Registration #5	2022-05-20	25.277 mi
Registration #6	2022-05-20	25.277 mi
Registration #7	2022-05-20	25.277 mi
Registration #8	2022-05-20	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3465 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1240 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	B2220059738