




report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Silver
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 2


Date	2021-11-19
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-15
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-03
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	34
Total items failed	0

MOT #12 2023-08-04 09:14

MOT test number 918594208255

Result ✓ Passed

Next expiry date 2024-08-03

- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
- Advice** Nearside Rear NSR Tyre worn on inner edge

MOT #11 2023-07-28 14:05

MOT test number 672425811671

Result ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
- Advice** Nearside Rear NSR Tyre worn on inner edge
- MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Nail in tyre
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))



MOT #10	2022-08-02 08:57
MOT test number	575526289795
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2022-08-01 10:28
MOT test number	869170933453
Result	✗ Failed
MAJOR	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8	2021-09-08 13:05
MOT test number	696394792630
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing and a nail in the tread (5.2.3 (d) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Valve stem slightly damaged (5.2.3 (j))

**MOT #7** 2021-09-07 11:19**MOT test number** 118195602241**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing and a nail in the tread (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2020-06-08 08:13**MOT test number** 840207923649**Result** ✓ Passed**MOT #5** 2019-06-17 14:52**MOT test number** 228565956004**Result** ✓ Passed**MOT #4** 2019-06-17 07:13**MOT test number** 291951722015**Result** ✗ Failed

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a))
- Minor** Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #3** 2018-06-16 09:30**MOT test number** 251304078312**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2017-06-17 10:30**MOT test number** 689616849861**Result** ✓ Passed**MOT #1** 2016-05-20 08:54**MOT test number** 868124990278**Result** ✓ Passed**Advice** Engine and underside covers fitted not allowing full inspection



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
3 August 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-06-14
Last registration	2023-08-04
Complete history	See info



Registration #1	2013-06-14	23 mi
Registration #2	2016-05-20	28.942 mi
Registration #3	2017-06-17	36.455 mi
Registration #4	2018-06-16	41.945 mi
Registration #5	2019-06-17	48.052 mi
Registration #6	2019-06-17	48.052 mi
Registration #7	2020-06-08	54.075 mi
Registration #8	2021-09-07	62.142 mi
Registration #9	2023-08-04	62.142 mi
Registration #10	2023-08-04	62.142 mi
Registration #11	2023-08-04	62.142 mi
Registration #12	2023-08-04	62.142 mi
Registration #13	2023-08-04	62.142 mi
Registration #14	2023-08-04	62.142 mi
Registration #15	2023-08-04	62.142 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1802 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1390 kg
Max. allowed weight	1890 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	2353086
---------------	---------