





report date: 2024-03-29

### General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Silver
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

### Entry 2

Date 2021-10-01

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-30	

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT #16	2022-09-08 15:10
MOT test number	827465870784
Result	<b>✓</b> Passed
Next expiry date	2023-09-20
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #15

MOT test number

418697810257

Result

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14		2020-07-27 13:38
MOT test i	number	776017120773
Result		✓ Passed
Advice	Rear Coil spring corroded Both Sides (5.3.1 (b) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Suspension arm corroded but not seriously weakened Both Sides (5.3.3 (b)	(i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #13** 2020-07-27 13:38 **MOT test number** 587406693035 Result × Failed Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Rear Suspension arm corroded but not seriously weakened Both Sides (5.3.3 (b) (i)) **Advice** Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Rear Coil spring corroded Both Sides (5.3.1 (b) (i)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #12	2019-03-30 11:33
MOT test number	578387615097
Result	<b>✓</b> Passed
Advice Rear Coil spring corroded Both Sides (5.3.1 (b) (i))	

MOT #11	2018-02-24 10:49
MOT test number	243587712113
Result	✓ Passed
MOT #10	2017-03-11 10:54
MOT test number	495223986709
Result	✓ Passed
MOT #9	2016-03-05 11:49
MOT test number	870981131491
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT** #7 2015-03-26 09:07 **MOT** test number 306055685066 Result × Failed **Notice** Engine covers fitted obscuring some components in the engine bay Fail Centre Exhaust has a major leak of exhaust gases (7.1.2) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Notice Under-trays fitted obscuring some underside components Notice Rear exhaust very corroded Fail Bonnet cannot be secured in the closed position (8.4.1)

MOT #6

MOT test number

237030984055

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Notice Rear exhaust very corroded

 MOT #5
 2013-03-28 14:03

 MOT test number
 379337883030

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #4		2013-03-28 14:03
MOT test number		628567083029
Result		<b>X</b> Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)	
Pass with rectification	Offside Headlamp aim too high (1.8)	

MOT #3	2012-10-18 11:06
MOT test number	508822492282
Result	<b>✓</b> Passed
Notice Nail in nearside front tyre	

MOT #2	2011-11-14 11:57
MOT test number	955498411338
Result	<b>✓</b> Passed
MOT #1	2010-11-11 16:49
MOT test number	970575910360
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FORD? How many owners define the check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	
***************************************	
HARMAN AND AND AND AND AND AND AND AND AND A	
***************************************	
*************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-16
Last registration	2022-09-08
Complete history	See info



Registration #1	2007-11-16	9 mi
Registration #2	2010-11-11	28.134 mi
Registration #3	2011-11-14	40.158 mi
Registration #4	2012-10-18	53.166 mi
Registration #5	2013-03-28	58.035 mi
Registration #6	2014-03-21	68.978 mi
Registration #7	2015-03-26	77.984 mi
Registration #8	2015-03-26	77.984 mi
Registration #9	2016-03-05	86.490 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		10.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/: