



Mercedes-Benz



J33PAE


report date: 2024-03-29

General information

| | |
|---------------------|------------------------------------|
| Make | MERCEDES-BENZ |
| Model | B-CLASS B200 CDI BLUEEFFICIENCY SE |
| Colour | Blue |
| Year of manufacture | 2014 |
| Top speed | 130 mph |
| 0 - 100 km/h | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------------|
| Power | 80 kW / 109 HP / 136 BHP |
| Max. torque | 250 Nm at 1.400 rpm |
| Engine capacity | 1.796 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 52.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 114 g/km |
| CO2 label | C |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-14 |
| Pictures | 15 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-05-17 |
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 6 |

MOT #10 2024-04-24 13:14

MOT test number 749416946905

Result ✓ Passed

Next expiry date 2025-05-17

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on edges close to cords replace asap (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge low on edges replace asap (5.2.3 (e))

MOT #9 2023-04-27 15:38

MOT test number 903017396347

Result ✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Chip in screen

**MOT #8**

2023-04-27 08:17

MOT test number

950219720731

Result**✗ Failed**

- Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Chip in screen
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge very close to cords replace asap (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge very close to cords replace asap (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7

2022-05-18 08:20

MOT test number

465756767656

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge replace asap (5.2.3 (e))

MOT #6

2021-06-22 15:00

MOT test number

669991145655

Result**✓ Passed****MOT #5**

2020-03-23 10:20

MOT test number

356833666440

Result**✓ Passed**

**MOT #4** 2019-03-29 13:19**MOT test number** 583505271028**Result** ✓ Passed**MOT #3** 2019-03-28 11:17**MOT test number** 108260535152**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside rear side light 50% working**MOT #2** 2018-03-02 10:09**MOT test number** 964577673008**Result** ✓ Passed**MOT #1** 2017-03-30 07:33**MOT test number** 367384535794**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
17 May 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 17 May 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.


Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-29 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2014-03-31 |
| Last registration | 2024-04-24 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-03-31 | 27 mi |
| Registration #2 | 2017-03-30 | 38.639 mi |
| Registration #3 | 2018-03-02 | 48.489 mi |
| Registration #4 | 2019-03-28 | 54.297 mi |
| Registration #5 | 2019-03-29 | 54.297 mi |
| Registration #6 | 2020-03-23 | 59.411 mi |
| Registration #7 | 2020-03-23 | 59.411 mi |
| Registration #8 | 2020-03-23 | 59.411 mi |
| Registration #9 | 2020-03-23 | 59.411 mi |
| Registration #10 | 2020-03-23 | 59.411 mi |
| Registration #11 | 2020-03-23 | 59.411 mi |
| Registration #12 | 2020-03-23 | 59.411 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 97% |
| Children | 81% |
| Pedestrian | 56% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2010 mm |
| Height | 1558 mm |
| Length | 4359 mm |
| Wheel base | 2699 mm |
| Kerb weight | 1475 kg |
| Max. allowed weight | 2030 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|-----------------|----------------|
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 65190132148311 |