





report date: 2024-03-28

#### General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	White
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

#### Entry 1

Date 2021-07-27

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

# MOT history

MOT expiry date	2025-03-28
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	19
Total items failed	5

MOT #16		2024-03-29 14:30
MOT test	number	468922103070
Result		✓ Passed
Next expi	ry date	2025-03-28
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excess	ive movement (5.3.4 (a)
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))		
Advice	Rear Brake hose has slight corrosion to ferrule Nearside & Offside (1.1.12	(f) (i))

MOT #15	2023-03-18 13:14
MOT test	number 797919042420
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side $(1.1.14 \; (a) \; (ii))$
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14		2023-03-18 13:14
MOT test number		165859192822
Result		<b>X</b> Failed
Advice Rear Brake disc	worn, pitted or scored, but not seriously weakened	d both side (1.1.14 (a) (ii))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a	n) (ii))
Advice Nearside Front	Tyre worn close to legal limit/worn on edge (5.2.3 (	e))

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #13** 2022-02-26 12:44

MOT test number 263428886311

**Result** 
✓ Passed

**MOT #12** 2021-03-01 09:54

MOT test number 607228228559

Result 

Passed

**MOT #11** 2021-02-26 18:21

**MOT test number** 721185178057

**Result** X Failed

**MAJOR** Offside Front Headlamp insecure (4.1.1 (c))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #10** 2020-02-26 15:31

**MOT test number** 641204356711

Result \( \sqrt{Passed} \)

**MOT #9** 2020-02-25 10:28

MOT test number 188024977211

Result × Failed

MAJOR Offside Front Side repeater not working door mirror. (4.4.1 (a) (ii))

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Bumper insecure front. (6.1.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8 2019-02-28 10:53

**MOT test number** 679536826282

**Result** 
✓ Passed

MOT #7 2018-02-27 12:35

**MOT test number** 396422189046

**Result** ✓ Passed

**MOT #6** 2017-03-03 15:56

**MOT test number** 751917830308

**Result** ✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #5** 2017-03-02 17:04

MOT test number 473901170794

Result X Failed

**Fail** Horn not working (1.6.2a)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**Fail** Front Windscreen washer provides insufficient washer liquid both (8.2.3)

MOT #4 2015-12-22 10:47

**MOT test number** 421534326437

**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #3** 2014-12-23 10:26

**MOT test number** 778887054305

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2 2013-12-12 15:26 **MOT test number** 175436643391 ✓ Passed Result MOT #1 2013-12-12 09:44 977736743355 **MOT test number X** Failed Result Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	28 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

**WG10DRX** 

report date: 2024-03-28

# For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>. More info

## Plate changes

See in this check if this TOYOTA had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-07
Last registration	2024-03-29
Complete history	See info



Registration #1	2010-06-07	10 mi
Registration #2	2013-12-12	25.172 mi
Registration #3	2013-12-12	25.172 mi
Registration #4	2014-12-23	29.746 mi
Registration #5	2015-12-22	34.132 mi
Registration #6	2017-03-02	36.595 mi
Registration #7	2017-03-03	36.596 mi
Registration #8	2018-02-27	49.716 mi
Registration #9	2019-02-28	64.462 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 12/13



WG10DRX report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
S0482	
50501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

# Additional information

Fuel tank capacity	32 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

**Engine number** 

1KR0998678