





General information

Make	MINI
Model	MINI COOPER
Colour	Grey
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E







Internet history

Entry 1

Date

2021-06-19

Pictures

4

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-22
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #11	2024-02-21 10:40	
MOT test number	867983780082	
Result	✓ Passed	
Next expiry date	2025-02-22	
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))		
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))		

MOT #10		2023-02-21 10:53
MOT test	number	373490293969
Result		✓ Passed
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))	

МОТ #9	2022-02-23 09:38
MOT test number	506282221776
Result	✓ Passed





MOT #8	2022-02-23 09:38
MOT test number	496217830431
Result	× Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)
MOT #7	2021-02-10 17:39
MOT test number	925193222816
Result	✓ Passed

МОТ #6	2020-02-21 11:41
MOT test number	118735504211
Result	✓ Passed

MOT #5	2019-02-21 09:21
MOT test number	748926728975
Result	✓ Passed

МОТ #4	2018-01-04 15:17
MOT test number	868481368462
Result	✓ Passed

MOT #3	2017-05-11 13:57
MOT test	number 661056485676
Result	✓ Passed
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Advice	Nearside Front wiper smearing but still clearing sufficiently





MOT #2	2017-05-11 08:37	
MOT test number	525145783288	
Result	🗙 Failed	
 Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Advice Nearside Front wiper smearing but still clearing sufficiently 		
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords		
(4.1.D.1a)		
MOT #1	2016-05-20 09:03	

MOT test number	285172845673
Result	✓ Passed
Advice Front Inner Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 22 February 2025
Tax status	Valid until 1 October
Days left	155
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-21
Last registration	2024-02-21
Complete history	See info



Registration #1	2013-05-21	17 mi
Registration #2	2016-05-20	21.836 mi
Registration #3	2017-05-11	28.174 mi
Registration #4	2017-05-11	28.174 mi
Registration #5	2018-01-04	31.836 mi
Registration #6	2019-02-21	43.648 mi
Registration #7	2020-02-21	53.108 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.117 mi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
\$0567	
\$0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Max. allowed weight	1735 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	B202J438 page 12/12