



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 S
Colour	Grey
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2023-10-05
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	22
Total items failed	29

MOT #19	2022-10-06 09:07
MOT test number	759488893854
Result	✓ Passed
Next expiry date	2023-10-05

MOT #18	2022-10-05 16:09
MOT test number	392081644858

Result	✗ Failed
--------	----------

- Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Rear exhaust back box missing
- Fail** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))

**MOT #17**

2021-09-28 09:49

MOT test number

907714446297

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

2021-09-27 11:56

MOT test number

721916567714

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Shock absorbers damaged to the extent that it does not function (5.3.2 (b))

MOT #15

2020-09-30 15:44

MOT test number

289450843160

Result

✓ Passed

**MOT #14**

2020-09-30 09:02

MOT test number

139549261118

Result**✗ Failed****Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Nail in tyre nail in shoulder**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt retaining clip missing (6.1.7 (g) (ii))**MOT #13**

2019-04-16 13:56

MOT test number

194048846158

Result**✓ Passed****MOT #12**

2019-04-16 13:30

MOT test number

719411375826

Result**✗ Failed****Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #11**

2018-04-24 10:27

MOT test number

818226550379

Result**✓ Passed**

**MOT #10** 2017-04-28 11:29**MOT test number** 243595718796**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2016-05-03 09:04**MOT test number** 549323932240**Result** ✓ Passed**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Nearside Rear tyre wearing on edge**Advice** Offside Front wiper blade**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front brake discs corrosion**MOT #8** 2015-04-30 19:24**MOT test number** 949330625162**Result** ✓ Passed**MOT #7** 2015-04-30 19:24**MOT test number** 335010425146**Result** ✗ Failed**Pass with rectification** Nearside rear brake recording little or no effort (3.7.B.5a)**MOT #6** 2014-04-29 10:27**MOT test number** 687429914187**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5**

2014-04-16 11:31

MOT test number

977166504166

Result**✗ Failed**

- Fail** Offside rear brake binding (3.7.B.1)
- Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside rear brake binding (3.7.B.1)
- Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #4

2013-05-01 17:15

MOT test number

608931023170

Result**✓ Passed****MOT #3**

2013-05-01 13:38

MOT test number

847331023186

Result**✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Notice** Offside front wiper smearing
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Service brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Brake performance not tested (3.7.A.1)



MOT #2	2012-04-12 12:50
MOT test number	947063202193
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-04-26 14:15
MOT test number	517186611189
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
30 June 2023

X

MOT

Expired:
5 October 2023

Tax status	Expired at 30 June 2023
Days left	305 days too late
MOT expiry date	5 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	FV08KUB
Plate since	2019-03-29
Current registration	FV08KUB
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-30
Last registration	2022-10-06
Complete history	See info



Registration #1	2008-04-30	25 mi
Registration #2	2011-04-26	34.345 mi
Registration #3	2012-04-12	45.398 mi
Registration #4	2013-05-01	55.453 mi
Registration #5	2013-05-01	55.453 mi
Registration #6	2014-04-16	64.176 mi
Registration #7	2014-04-29	64.492 mi
Registration #8	2015-04-30	73.904 mi
Registration #9	2016-05-03	81.268 mi
Registration #10	2017-04-28	88.646 mi
Registration #11	2018-05-01	95.024 mi
Registration #12	2019-05-01	101.402 mi
Registration #13	2020-05-01	107.780 mi
Registration #14	2021-05-01	114.158 mi
Registration #15	2022-05-01	120.536 mi
Registration #16	2023-05-01	126.914 mi
Registration #17	2024-05-01	133.292 mi
Registration #18	2025-05-01	139.670 mi
Registration #19	2026-05-01	146.048 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1821 mm
Height	1519 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1378 kg
Max. allowed weight	1804 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBAV0010082