

Ford



## General information

Make	FORD
Model	RANGER XL 4X4 DCB TDCI
Colour	Red
Year of manufacture	2010
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	140 BHP	0 < 101 A
Engine capacity	2.500 cc	101 - 120 <sup>B</sup> <sub>C</sub>
Cylinders	4	121 - 140 E
Fuel type	Diesel	141 - 165 <b>6</b>
Consumption city	21.9 mpg	166 - 185 H
Consumption extra urban	31.4 mpg	186 - 225 J
Consumption combined	27.2 mpg	225+ L





Internet history	
Entry 1	
Date	2021-08-05
Pictures	0
Listing price	View report

source: cargurus.co.uk



# MOT history

MOT expiry date	2025-02-28
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	20
Total items failed	10

MOT #15	2024-03-01 15:21
MOT test number	329820123626
Result	✓ Passed
Next expiry date	2025-02-28
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

MOT #14	2024-02-23 15:01	
MOT test number	590485429721	
Result	🗙 Failed	
<b>Fail</b> Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))		
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
<b>Fail</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))		

MOT #13	2023-11-08 15:37
MOT test number	562127057894
Result	✓ Passed
Advice Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	



FV60CXO
report date: 2024-03-28

MOT #12	2023-11-06 11:38
MOT test number	976985832524
Result	🗙 Failed
FailRear Exhaust silencer insecure (8.1.1 (b) (i))	
Advice Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
FailNearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #11	2022-10-04 07:32
MOT test number	532977228054
Result	✓ Passed
Advice Tyre worn close to legal limit/worn on edge ALL FOUR TYRES FRONT	& REAR (5.2.3 (e))

MOT #10	2021-08-21 08:49
MOT test number	201000717037
Result	✓ Passed

MOT #9		2021-08-19 11:53
MOT te	st number	900081799764
Result		× Failed
Fail	Offside Front Brake pipe excessively corroded Front To Rear (1.1.11 (c))	
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))	
Fail	Rear Brake pipe excessively corroded All Rear Pipes (1.1.11 (c))	
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))	



FV60CXO
report date: 2024-03-28

MOT #8		2021-01-05 12:59
MOT test	number	416834772921
Result		✓ Passed
Advice	N/s/ and o/s rear tyres treads 3mm	
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))	
Advice	General corrosion on underside of vehicle	
Advice	O/s/f tyre tread 4mm	
Advice	Fuel Pipe/s corroded	

MOT #7		2019-12-31 14:38
MOT test n	umber	935372276255
Result		✓ Passed
Advice	Corrosion started on underside of vehicle	
Advice	Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))	

MOT #6		2018-11-29 09:49
MOT test	number	686085393747
Result		Passed
Advice	Brake pipe corroded, covered in grease or other material All rear (1.1.11 (c))	
Advice	Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c	))

MOT #5	2017-12-07 11:46
MOT test number	778544268346
Result	✓ Passed

MOT #4	2016-12-15 11:25
MOT test number	203983506206
Result	✓ Passed



**FV60CXO** report date: 2024-03-28

МОТ #3		2015-12-07 11:39
MOT test number		394186185258
Result		✓ Passed
	nt Tyre worn close to the legal limit (4.1.E.1) ear Tyre worn close to the legal limit (4.1.E.1)	
MOT #2		2014-09-04 14:41

MOT test number	745667844225
Result	✓ Passed
MOT #1	2013-09-16 10:45
MOT test number	795369153237
Result	✓ Passed



FV60CX0 report date: 2024-03-28

Tax & MOT check

✓ Taxed	✓ МОТ
<b>Tax due:</b> 1 April 2025	Expires: 28 February 2025
Tax status	Valid until 1 April
Days left	338
MOT expiry date	28 February 2025
Full MOT history	See MOT history





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	 
Category	 AMPL
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-30
Last registration	2024-03-01
Complete history	See info



Registration #1	2010-09-30	11 mi
Registration #2	2013-09-16	50.627 mi
Registration #3	2014-09-04	60.939 mi
Registration #4	2015-12-07	77.977 mi
Registration #5	2016-12-15	88.196 mi
Registration #6	2017-12-07	95.510 mi
Registration #7	2018-11-29	101.341 mi
Registration #8	2019-12-31	105.559 mi
Registration #9	2021-01-05	110.000 mi
Registration #10		11.117 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 mi





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1788 mm
Height	805 mm
Length	5080 mm
Kerb weight	1845 kg
Max. allowed weight	2985 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5