



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI COMFORT
Colour	Black
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2024-01-27
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	64
Total items failed	5

**MOT #17**

2024-01-25 17:15

MOT test number

483798433786

Result**✗ Failed**

- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))
- MAJOR** Nearside Front Direction indicator missing (4.4.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Windscreen washer not working (3.5 (a))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Body component damaged and likely to cause injury (6.2.1 (a) (i))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #16** 2023-01-28 10:03**MOT test number** 175733353337**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2023-01-28 10:03**MOT test number** 210181928547**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2022-01-04 16:28**MOT test number** 203972923520**Result** ✓ Passed**MOT #13** 2022-01-04 12:30**MOT test number** 716964652145**Result** ✗ Failed**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2021-01-12 16:18**MOT test number** 820102995864**Result** ✓ Passed**MOT #11** 2019-10-14 10:35**MOT test number** 413178031826**Result** ✓ Passed

- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Nearside Front BRAKE IS BINDING ON U/L
- Advice** Front Tyre worn close to legal limit/worn on edge BOTH, edges (5.2.3 (e))

MOT #10 2019-10-12 10:27**MOT test number** 680479114646**Result** ✗ Failed

- Advice** Foot brake pedal ,little travel
- DANGEROUS** Stop lamp(s) all not working (4.3.1 (a) (iii))
- MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Advice** Front Tyre worn close to legal limit/worn on edge BOTH, edges (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement FRONT (5.3.4 (a) (i))
- Advice** Nearside Rear BRAKE IS BINDING ON U/L
- MAJOR** Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- DANGEROUS** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn FRONT (5.3.4 (a) (i))
- Advice** Nearside Front BRAKE IS BINDING ON U/L
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))

**MOT #9** 2018-10-12 15:11**MOT test number** 340884634077**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Auxiliary drive belt deteriorated**Advice** Tyres worn on edges**MOT #8** 2018-10-12 15:11**MOT test number** 791157929545**Result** ✗ Failed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Auxiliary drive belt deteriorated**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Tyres worn on edges**MOT #7** 2017-10-13 16:46**MOT test number** 848411188506**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 205/55/16, & perishing (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 205/55/16, & perishing (4.1.E.1)**MOT #6** 2016-10-17 15:34**MOT test number** 574931583902**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement d bush (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2016-10-17 12:54**MOT test number** 922823600743**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement d bush (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-10-20 10:17**MOT test number** 290343484311**Result** ✓ Passed**Advice** Traction control light on**MOT #3** 2015-03-23 10:36**MOT test number** 988882585072**Result** ✓ Passed**MOT #2** 2014-03-25 08:51**MOT test number** 415764084034**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2014-03-25 08:51
MOT test number	198704584451
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Pass with rectification	Offside Headlamp aim too high (1.8)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2024

X

MOT

Expired:
27 January 2024

Tax status	Expired at 1 February 2024
Days left	88 days too late
MOT expiry date	27 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	SD11NPN
Plate since	2019-03-28
Current registration	SD11NPN
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-30
Last registration	2024-01-25
Complete history	See info



Registration #1	2011-03-30	13 mi
Registration #2	2014-03-25	24.294 mi
Registration #3	2015-03-23	32.196 mi
Registration #4	2015-10-20	36.767 mi
Registration #5	2016-10-17	49.156 mi
Registration #6	2016-10-17	49.156 mi
Registration #7	2017-10-13	60.148 mi
Registration #8	2018-10-12	74.517 mi
Registration #9	2018-10-12	74.517 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1490 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1395 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D4FBBZ282915
---------------	--------------