





report date: 2024-03-28

# General information

Make	HYUNDAI
Model	I20 ACTIVE
Colour	Blue
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	12.9 seconds
Gearbox	4 speed automatic

# Engine & fuel consumption

Power	99 BHP
Max. torque	137 Nm at 4.200 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history


### Entry 2

Date 2022-04-26

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-05-08
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	9
Total items failed	4

MOT #10	2023-05-03 15:07
MOT test number	560386254975
Result	✓ Passed
Next expiry date	2024-05-08
Advice Front Brake pad(s) wearing thin **Caution** Close to 1.5mm limit (1.1.13 (a) (ii))	

MOT #9	2023-05-03 13:18
MOT test number	768045964933
Result	<b>×</b> Failed
Advice Front Brake pad(s) wearing thin **Caution** Close to 1.5mm limit (1.1.13 (a) (ii)  Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a))	)

MOT #8	2022-05-09 09:57
MOT test number	209595106515
Result	<b>✓</b> Passed
MOT #7	2021-07-19 13:09
MOT test number	913268681204
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #5
 2020-07-29 14:59

 MOT test number
 539427458889

 Result
 ✓ Passed

 MOT #4
 2019-04-23 13:14

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

MOT test number


Result

Advice All tyres starting to crack on tread and sidewall

CarCheck.co.uk page 4/12



report date: 2024-03-28



MOT #1	2017-04-25 13:59
MOT test number	217864823865
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	8 May 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

SD14SDU

report date: 2024-03-28

# For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-04-28
Last registration	2023-05-03
Complete history	See info



Registration #1	2014-04-28	29 mi
Registration #2	2017-04-25	14.649 mi
Registration #3	2018-04-24	24.385 mi
Registration #4	2018-04-24	24.385 mi
Registration #5	2019-04-23	39.608 mi
Registration #6	2020-07-29	54.037 mi
Registration #7		11.777 mi
Registration #8		0.00 44
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 no

More info >

CarCheck.co.uk page 11/12




report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



# Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1156 kg
Max. allowed weight	1565 kg

### Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1.	2/12

Number of axles 2

**Engine number** G4FAEU017573