



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI STYLE
Colour	Grey
Year of manufacture	2012
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-25
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	8

MOT #13	2023-07-03 13:47
MOT test number	334332733603
Result	✓ Passed
Next expiry date	2024-07-04

MOT #12	2022-07-05 12:23
MOT test number	716333092208
Result	✓ Passed

MOT #11	2021-07-05 12:20
MOT test number	527636483923
Result	✓ Passed

MOT #10	2021-07-02 10:14
MOT test number	656709194045
Result	✗ Failed
Fail	Central Front Brake lever has insufficient reserve travel (1.1.2 (a))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Offside Rear Service brake grabbing severely (1.2.1 (c))

**MOT #9** 2020-11-05 12:18**MOT test number** 314724892514**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-11-04 10:54**MOT test number** 411542063637**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #7** 2019-11-12 17:18**MOT test number** 507429206834**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2018-11-16 14:43**MOT test number** 343663935330**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #5** 2017-11-14 14:58**MOT test number** 780790055786**Result** ✓ Passed**MOT #4** 2016-11-17 10:01**MOT test number** 432049042891**Result** ✓ Passed**MOT #3** 2016-06-28 14:18**MOT test number** 322903258530**Result** ✓ Passed**MOT #2** 2015-11-20 09:54**MOT test number** 636780715357**Result** ✓ Passed**MOT #1** 2015-11-20 09:54**MOT test number** 579327948569**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working both (1.1.C.1d)**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
4 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	BD62NHX
Plate since	2019-09-28
Current registration	BD62NHX
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-22
Last registration	2023-07-03
Complete history	See info



Registration #1	2012-11-22	18 mi
Registration #2	2015-11-20	45.357 mi
Registration #3	2015-11-20	45.357 mi
Registration #4	2016-06-28	54.186 mi
Registration #5	2016-11-17	55.378 mi
Registration #6	2017-11-14	58.237 mi
Registration #7	2018-11-16	61.453 mi
Registration #8	2019-11-12	69.475 mi
Registration #9	2020-05-20	75.377 mi
Registration #10	2020-05-20	75.377 mi
Registration #11	2020-05-20	75.377 mi
Registration #12	2020-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2020-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1660 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDCZ126759