



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D S
Colour	Green
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-23
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	11
Total items failed	5

MOT #18	2023-06-15 11:35
MOT test number	387973040021
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Steering rack weap

MOT #17	2022-06-17 11:21
MOT test number	447424346639
Result	✓ Passed

MOT #16	2022-06-16 13:43
MOT test number	528957422897
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
DANGEROUS	Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Central Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2021-06-07 12:18
MOT test number	483275716191
Result	✓ Passed

**MOT #14** 2020-06-11 10:41**MOT test number** 483736781913**Result** ✓ Passed**MOT #13** 2020-06-11 10:41**MOT test number** 402770301187**Result** ✗ Failed**Pass with rectification** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt
(2.1.3 (g) (ii))**MOT #12** 2019-06-12 15:21**MOT test number** 514735667365**Result** ✓ Passed**MOT #11** 2018-06-08 13:01**MOT test number** 501997293645**Result** ✓ Passed**MOT #10** 2017-06-27 11:39**MOT test number** 423942472559**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #9** 2016-06-22 14:18**MOT test number** 566039768187**Result** ✓ Passed



MOT #8	2016-06-22 11:40
MOT test number	565000565204
Result	✗ Failed
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #7	2015-06-25 12:56
MOT test number	689176175138
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #6	2014-06-26 09:02
MOT test number	798557874109
Result	✓ Passed

MOT #5	2014-06-25 14:05
MOT test number	216866074121
Result	✗ Failed
Fail	Nearside Front Road wheel cracked (4.2.A.1a)

MOT #4	2013-06-27 15:40
MOT test number	225208973402
Result	✓ Passed

MOT #3	2013-06-26 14:55
MOT test number	465267073185
Result	✗ Failed
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)



MOT #2	2012-06-27 15:16
MOT test number	278419672477
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2012-06-27 15:16
MOT test number	426809372193
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

X

Untaxed

Tax expired:
14 November 2023

✓

MOT

Expires:
30 June 2024

Tax status	Expired at 14 November 2023
Days left	167 days too late
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-06-30
Last registration	2023-06-15
Complete history	See info



Registration #1	2009-06-30	10 mi
Registration #2	2012-06-27	10.019 mi
Registration #3	2013-06-26	13.561 mi
Registration #4	2013-06-27	13.561 mi
Registration #5	2014-06-25	16.898 mi
Registration #6	2014-06-26	16.898 mi
Registration #7	2015-06-25	19.517 mi
Registration #8	2016-06-22	22.308 mi
Registration #9	2016-06-22	22.308 mi
Registration #10	2017-06-27	24.184 mi
Registration #11	2018-06-27	25.000 mi
Registration #12	2019-06-27	25.000 mi
Registration #13	2020-06-27	25.000 mi
Registration #14	2021-06-27	25.000 mi
Registration #15	2022-06-27	25.000 mi
Registration #16	2023-06-27	25.000 mi
Registration #17	2024-06-27	25.000 mi
Registration #18	2025-06-27	25.000 mi
Registration #19	2026-06-27	25.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

591583