




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA LIFE CDTI 8V
Colour	Silver
Year of manufacture	2008
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-10-09
Pictures	2
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-27
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	82
Total items failed	4

MOT #22	2023-07-25 12:34
MOT test number	218005694010
Result	✓ Passed
Next expiry date	2024-07-27
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2023-07-24 11:42

MOT test number

339656234951

Result**✗ Failed**

- MAJOR** Horn not working (7.7 (a))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #20

2022-07-28 12:50

MOT test number

331557153803

Result**✓ Passed**

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear suspension components corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Stop lamp(s) lens defective which has no effect on emitted light cracked (4.3.1 (b) (i))
- Advice** Exhaust mounting defective (6.1.2 (a))

**MOT #19**

2022-07-27 12:41

MOT test number

865871038176

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear suspension components corroded
- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Stop lamp(s) lens defective which has no effect on emitted light cracked (4.3.1 (b) (i))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18

2021-07-28 09:37

MOT test number

522422154449

Result**✓ Passed**

- Advice** Rear exhaust back box mounting corroded
- Advice** Rear brake pipes undersealed and coated in grease

MOT #17

2021-07-28 09:37

MOT test number

747829085329

Result**✗ Failed**

- Advice** Rear brake pipes undersealed and coated in grease
- Advice** Rear exhaust back box mounting corroded
- Pass with rectification** Front Headlamp aim too low Both (4.1.2 (a))

**MOT #16**

2020-09-23 15:20

MOT test number

838909778803

Result

✓ Passed

- Advice** Handbrake lever little reserve travel
- Advice** Sill covers fitted
- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Rear seat upright release lever missing seat secured in upright position

MOT #15

2020-09-23 10:12

MOT test number

497272307250

Result

✗ Failed

- Advice** Nearside Rear seat upright release lever missing seat secured in upright position
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Handbrake lever little reserve travel
- Advice** Sill covers fitted
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #14

2019-09-18 15:17

MOT test number

295882074340

Result

✓ Passed

- Advice** High brake high travel
- Advice** Rear tyres slightly worn on edges
- Advice** Offside Rear light lens repaired with tape
- Advice** Centre exhaust hanger corroded off

**MOT #13**

2019-09-18 08:59

MOT test number

292082370678

Result**✗ Failed****DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** High brake high travel**MAJOR** Horn not working (7.7 (a) (ii))**Advice** Rear tyres slightly worn on edges**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear light lens repaired with tape**MAJOR** Front Sub-frame damaged and seriously weakened (5.3.3 (b) (i))**Advice** Centre exhaust hanger corroded off**MOT #12**

2018-09-19 13:18

MOT test number

758395527010

Result**✓ Passed****Advice** Offside headlight lens repaired with tape & condensated**Advice** Exhaust heat shield poorly secured**Advice** Hand brake high travel**Advice** Undertrays and engine covers fitted

**MOT #11**

2018-09-17 13:10

MOT test number

327056740055

Result**✗ Failed****MAJOR** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))**Advice** Offside headlight lens repaired with tape & condensated**Advice** Exhaust heat shield poorly secured**MAJOR** Exhaust has a major leak of exhaust gases from flexi (6.1.2 (a))**MAJOR** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))**Advice** Hand brake high travel**Advice** Undertrays and engine covers fitted**MOT #10**

2017-09-20 09:33

MOT test number

541879581312

Result**✓ Passed****Advice** Front brake discs corroded**Advice** Engine covers and under trays fitted**Advice** Exhaust head shield insecure**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Exhaust poor condition and exhaust hanger corroded off

**MOT #9** 2017-09-20 08:51**MOT test number** 348614841126**Result** ✗ Failed

- Advice** Engine covers and under trays fitted
- Advice** Exhaust head shield insecure
- Fail** Horn not working (1.6.2a)
- Advice** Exhaust poor condition and exhaust hanger corroded off
- Advice** Front brake discs corroded
- Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #8 2016-09-05 10:19**MOT test number** 839529012074**Result** ✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Undertrays and sill covers fitted
- Advice** Front brake discs slight corrosion and brake pads appear low
- Advice** Both front tyres starting to wear low
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** 1 rear exhaust hanger corroded off (system still secure)
- Advice** Exhaust heat shield loose

MOT #7 2015-09-17 14:11**MOT test number** 540193032164**Result** ✓ Passed

**MOT #6** 2015-09-17 14:11**MOT test number** 776501676047**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2014-09-03 09:27**MOT test number** 428976244280**Result** ✓ Passed**MOT #4** 2013-09-10 14:53**MOT test number** 139483853211**Result** ✓ Passed**MOT #3** 2012-09-11 11:23**MOT test number** 996695152253**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2011-09-09 15:59**MOT test number** 215272551204**Result** ✓ Passed**MOT #1** 2011-09-09 15:33**MOT test number** 307982751235**Result** ✗ Failed**Fail** Rear Parking brake lever has no reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history


For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FE58BZJ
Plate since	2024-03-29
Current registration	 FE58BZJ
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-09-30
Last registration	2023-07-25
Complete history	See info



Registration #1	2008-09-30	23 mi
Registration #2	2011-09-09	13.638 mi
Registration #3	2011-09-09	13.638 mi
Registration #4	2012-09-11	31.906 mi
Registration #5	2013-09-10	47.857 mi
Registration #6	2014-09-03	57.482 mi
Registration #7	2015-09-17	68.981 mi
Registration #8	2015-09-17	68.981 mi
Registration #9	2016-09-05	78.714 mi
Registration #10	2017-09-20	86.910 mi
Registration #11	2017-09-20	86.910 mi
Registration #12	2018-09-17	93.511 mi
Registration #13	2018-09-19	93.540 mi
Registration #14	2019-09-09	93.540 mi
Registration #15	2019-09-09	93.540 mi
Registration #16	2019-09-09	93.540 mi
Registration #17	2019-09-09	93.540 mi
Registration #18	2019-09-09	93.540 mi
Registration #19	2019-09-09	93.540 mi
Registration #20	2019-09-09	93.540 mi
Registration #21	2019-09-09	93.540 mi
Registration #22	2019-09-09	93.540 mi
Registration #23	2019-09-09	93.540 mi
Registration #24	2019-09-09	93.540 mi
Registration #25	2019-09-09	93.540 mi



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1510 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	6115051