





report date: 2024-03-29

## General information

| Make                | HYUNDAI           |
|---------------------|-------------------|
| Model               | TUCSON GDI SE NAV |
| Colour              | Black             |
| Year of manufacture | 2019              |
| Top speed           | 113 mph           |
| Gearbox             | 6 speed Manual    |

# Engine & fuel consumption

| Power                   | 130 BHP             |
|-------------------------|---------------------|
| Max. torque             | 161 Nm at 4.850 rpm |
| Engine capacity         | 1.591 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 34.4 mpg            |
| Consumption extra urban | 44.1 mpg            |
| Consumption combined    | 34.9 mpg            |
| CO2 emission            | 162 g/km            |
| CO2 label               | G                   |



CarCheck.co.uk page 1/10



### Internet history

### Entry 1

Date 2022-04-09

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date    | 2025-04-04 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 1          |
| Total advice items | 3          |
| Total items failed | 1          |

| MOT #4   | 2024-04-05 09:17 |
|--|------------------|
| MOT test number  | 277458949218     |
| Result   | ✓ Passed         |
| Next expiry date   | 2025-04-04       |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |

| MOT #3  | 2024-04-05 09:17 |  |
|---|------------------|--|
| MOT test number   | 746476377432     |  |
| Result  | <b>★</b> Failed  |  |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))  |                  |  |
| Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |                  |  |

| MOT #2                   | 2023-03-30 09:34 |
|--------------------------|------------------|
| MOT test number          | 259026016142     |
| Result                   | <b>✓</b> Passed  |
| Advice Coolant level low |                  |

| MOT #1          | 2022-03-31 08:50 |
|-----------------|------------------|
| MOT test number | 137308173968     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status       | Valid until 1 October |
|------------------|-----------------------|
| Days left        | 154                   |
| MOT expiry date  | 4 April 2025          |
| Full MOT history | See MOT history       |

### Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | I          |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |


CarCheck.co.uk page 4/10



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



**DV19LCU** 

report date: 2024-03-29

| Owner   | hictor.  |
|---------|----------|
| UWNEI   | nisioiv  |
| OVVIICI | THISCOLY |

| e when miscery   |           |      |
|--|-----------|------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is  |           | NDAI |
|  |           |      |
|  |           |      |
| ***************************************  |           |      |
|  |           |      |
| ***************************************  |           |      |
| THE PROPERTY OF THE PROPERTY O |           |      |
|  | More info | >    |
| Plate changes  |           |      |
| See in this check if this HYUNDAI had different number plates.   |           |      |
| Number of plates   |           |      |
| Current registration   | UK UK     |      |
| Plate since  |           |      |
| Current registration   | NK NK     |      |
| Plate since  |           |      |
|  | More info | >    |

CarCheck.co.uk page 7/10



### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



**DV19LCU** 

report date: 2024-03-29

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2019-03-31 |
| Last registration          | 2024-04-05 |
| Complete history           | See info   |



| Registration #1 | 2019-03-31 | 29 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2022-03-31 | 13.518 mi |
| Registration #3 |            | 11.777 es |
| Registration #4 |            | 71.777 66 |
| Registration #5 |            | 11.777 es |
| Registration #6 |            |           |

Registration #6

More info >

CarCheck.co.uk page 9/10



**DV19LCU** 

report date: 2024-03-29

### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| 50567 |                  |
| 50569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 86%             |
| Children       | 85%             |
| Pedestrian     | 71%             |
| Safety systems | 71%             |
| Overall rating | 80%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1850 mm |
|---------------------|---------|
| Height              | 1650 mm |
| Length              | 4475 mm |
| Wheel base          | 2670 mm |
| Kerb weight         | 1414 kg |
| Max. allowed weight | 2030 kg |

## Additional information

| Fuel tank capacity                | 62 I             |      |
|-----------------------------------|------------------|------|
| Fuel delivery                     | Direct Injection |      |
| Number of doors                   | 5                |      |
| Number of seats<br>CarCheck.co.uk | 5 page 1         | 0/10 |

Number of axles 2

Engine number G4FDKZ811474