




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H



**MOT history****MOT expiry date** 2021-01-30**MOT pass rate** 63 %**MOT passed** 10**Failed MOT tests** 6**Total advice items** 35**Total items failed** 10**MOT #16** 2020-01-23 15:39**MOT test number** 397882549269**Result** ✓ Passed**Next expiry date** 2021-01-30

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15 2020-01-23 12:16**MOT test number** 816368158077**Result** ✗ Failed

- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Exhaust system insecure (6.1.2 (a))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2019-01-25 16:59

MOT test number

232554551033

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust mounting defective (6.1.2 (a))

MOT #13

2019-01-25 12:06

MOT test number

354226029254

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust mounting defective (6.1.2 (a))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2018-01-31 14:23

MOT test number

739409837437

Result

✓ Passed

MOT #11

2016-08-27 10:32

MOT test number

593823035516

Result

✓ Passed

**MOT #10** 2016-08-27 10:32**MOT test number** 417155807714**Result** ✗ Failed

- Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #9 2015-09-08 10:50**MOT test number** 147872819887**Result** ✓ Passed**MOT #8** 2015-09-01 16:19**MOT test number** 625063555980**Result** ✗ Failed

- Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #7 2014-08-01 16:23**MOT test number** 346393414416**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-08-01 09:26**MOT test number** 705033414250**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the right. (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside coil spring broken (2.4.C.1a)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-07-16 16:24**MOT test number** 918507893125**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Crack in windscreen**MOT #4** 2013-07-16 12:08**MOT test number** 506487593160**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Crack in windscreen**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2012-08-03 13:05**MOT test number** 585386212279**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-08-02 11:38**MOT test number** 168124311225**Result** ✓ Passed**MOT #1** 2010-08-05 14:20**MOT test number** 113017210259**Result** ✓ Passed**Notice** Offside front and nearside front tyres getting low in tread.



Tax & MOT check

✕
Untaxed

Tax expired:
25 January 2021

✕
MOT

Expired:
30 January 2021

Tax status	Expired at 25 January 2021
Days left	1190 days too late
MOT expiry date	30 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 HN57VHT
Plate since	2019-03-29
Current registration	 HN57VHT
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-11-29
Last registration	2020-01-23
Complete history	See info



Registration #1	2007-11-29	12 mi
Registration #2	2010-08-05	25.705 mi
Registration #3	2011-08-02	40.117 mi
Registration #4	2012-08-03	50.011 mi
Registration #5	2013-07-16	57.669 mi
Registration #6	2013-07-16	57.669 mi
Registration #7	2014-08-01	66.107 mi
Registration #8	2014-08-01	66.107 mi
Registration #9	2015-09-01	77.417 mi
Registration #10	2016-09-01	88.727 mi
Registration #11	2017-09-01	100.037 mi
Registration #12	2018-09-01	111.347 mi
Registration #13	2019-09-01	122.657 mi
Registration #14	2020-09-01	133.967 mi
Registration #15	2021-09-01	145.277 mi
Registration #16	2022-09-01	156.587 mi
Registration #17	2023-09-01	167.897 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118