





report date: 2024-03-28

## General information

Make	MAZDA
Model	CX-5 D SE-L NAV
Colour	Red
Year of manufacture	2014
Top speed	126 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

Entr	. 1
EIIU	vт

Lifety 1	
Date	2021-06-03
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



VO14WKN report date: 2024-03-28

MOT history

MOT expiry date	2025-04-11
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #8	2024-04-11 10:28
MOT test number	101447949359
Result	✓ Passed
Next expiry date	2025-04-11
Advice General vehicle condition corroded, suspension components corroded, front and rear, control arms, suspension arms, sub frames	

MOT #7	2023-03-29 10:32
MOT test number	587149757407
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6		2022-03-29 12:00
MOT test	number	143730935593
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



**Advice** 

VO14WKN

report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Osr brakedisc heavily corroded on outer face

MOT #4

MOT test number

Result

MOT #3

Result

2021-04-12 08:51

\*\*Passed\*\*

MOT #3

2020-03-13 14:20

MOT test number

660379593369

Result

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #2
 2019-03-13 16:47

 MOT test number
 107382227510

 Result
 ✓ Passed

 MOT #1
 2017-07-24 10:03

 MOT test number
 630755752084

 Result
 ✓ Passed

 Advice
 Offside Front Outer Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	11 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
**************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-07-30
Last registration	2024-04-11
Complete history	See info



Registration #1	2014-07-30	19 mi
Registration #2	2017-07-24	32.292 mi
Registration #3	2019-03-13	47.877 mi
Registration #4	2020-03-13	57.698 mi
Registration #5	2021-04-12	69.051 mi
3		
Registration #6		0.00 44
		11.777 ea 11.777 ea
Registration #6		11.777 ea 11.777 ea 11.777 ea
Registration #6 Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Safety ratings

NCAP rating	****
Adult	94%
Children	87%
Pedestrian	64%
Safety systems	86%
Overall rating	86%
Video	see crash video



# Dimensions & weight

Width	1840 mm
Height	1670 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1450 kg
Max. allowed weight	2035 kg

# Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30362977

CarCheck.co.uk page 11/11